Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



© 2016 Mazda Motor of America, Inc.

Subject: Bulletin No: 09-009/16

HANDS-FREE BLUETOOTH MODULE AND/OR TEXT MESSAGING TROUBLE-SHOOTING PROCEDURE

Last Issued: 05/10/2016

BULLETIN NOTE

This bulletin supersedes the previously issued bulletin(s) listed below. The changes are noted in Red beside the change bars.

Previous TSBs:	Date(s) Issued:	Previous TSBs:	Date(s) Issued:
09-009/16	02/17/16	09-014/12	03/16/12 and 08/10/12
09-039/14	09/09/14	09-008/11	02/23/11
09-019/13	06/14/13	09-007/10	02/08/10
		09-042/08	12/23/08

APPLICABLE MODEL(S)/VINS

2016 CX-3	2007-2016 CX-9	2009-2016 Mazda6
2013-2016 CX-5	2010-2016 Mazda3	2009-2016 MX-5
2009-2012 CX-7	2008-2015 Mazda5	2009-2011 RX-8

Applies only to models equipped with Hands-Free Bluetooth

DESCRIPTION

Some vehicles may exhibit BLUETOOTH® hands-free and/or text messaging related concerns.

To improve the handling of BLUETOOTH® hands-free and/or text messaging customer concerns, Mazda created a special service and parts exchange program as of February 2010.

Customers experiencing related concerns should have their vehicle and/or device inspected according to the following procedure.

Bulletin No: 09-009/16	Last Issued: 05/10/2016
© 2016 Mazda Motor of America, Inc.	

REPAIR PROCEDURE

- 1. Verify customer concern.
- 2. Verify that the customer has provided the correct phone or device.
- 3. Confirm the device compatibility by web or smartphone.

	Go to:	
By Web	www.MazdaUSA.com/Bluetooth	
By Smartphone	Smartphone MyMazda app; press MAZDA CONNECT	

NOTE:

I

- When checking compatibility, be aware that phones may be approved for some functions but not for others.
- Scroll down to make sure there are no red X's in the compatibility list.
- Check the phone model number; compatability can vary by the phone company version.
- 4. Check MS3 Online (Mazda Service Support System) for related service bulletins and service alerts.
- 5. If the steps above did not resolve the customer's concern, contact Mazda Hands-Free System Customer Care at (800) 430-0153 to review the concern further.

NOTE:

- If for any reason there was a mis-communication regarding the concern written on the RO, the Mazda Hands-Free System Customer Care representative can clarify it.
- If Mazda Hands-Free System Customer Care has provided you a case number, they have determined there could be a problem with the hands-free module. However, a case number does not mean automatic module replacement. Proceed to next step.
- Troubleshoot the vehicle according to the instruction on MS3 online or the Workshop Manual (Section 09 > Body and Accessories > On-Board Diagnostics).
 - If the cause cannot be determined through MS3 online or the Workshop Manual, contact the Mazda Technical Hotline for assistance and support.

NOTE: The Mazda Technical Assistance Hotline does not provide authorization for warranty or parts ordering.

- If it is determined that a replacement hands-free module is required, proceed to next step.

NOTE: Provide the case number to your parts dept. so they can order the part.

- 7. Replace the hands-free module according to the instruction on MS3 online or the Workshop Manual (Section 09 > Body and Accessories > Entertainment > Bluetooth Unit Removal/Installation).
- 8. Verify the repair.

Bulletin No: 09-009/16	Last Issued: 05/10/2016
© 2016 Mazda Motor of America, Inc.	

PARTS INFORMATION

Review the points below when ordering a hands-free Bluetooth unit:

NOTE:

- Use the Mazda Hands-Free System Customer Care case number to place the order with United Radio for the part exchange.
- It is not necessary to call United Radio directly, place the order online, via the United Radio Website.

	Access the United Radio Website using either one of the links below:
1	Go to: https://portal.mazdausa.com/dealershome/service_parts/dag/exchange_page_1.htm Then select "United Radio Website" and log in.
	OR
2	Go to: http://Dealers.mazdausa.com/
	Then select "Parts and Accessories", "Parts", "Exchange Central", then select "United Radio Website" and log in.

WARRANTY INFORMATION

NOTE: For this TSB only, dealers may use actual time (up to a maximum of 0.9 hr.) to cover any necessary diagnostic time.