

Technical Service Bulletin



90 Audi virtual cockpit - speed warning does not work

90 16 67 2043734/2 April 12, 2016. Supersedes Technical Service Bulletin Group 90 number 16-64 dated March 22, 2016 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q7	2017	All	With Audi virtual cockpit

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header data (Corrected Elsa display error)
1	3/22/2016	Initial publication

After a threshold for the speed warning in the MMI is set and then turned off, one or both of the following conditions occurs:

- The speed warning cannot be deactivated.
- The speed warning is displayed in km/h and not mph.

Technical Background

Software deviation.

Production Solution

Optimized software in production.

Service

Note:

The software of the Audi virtual cockpit must be updated with an SD card (part number 8S0906961H), which should be ordered in advance.

SVM Update Instructions

1. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions*.
2. Update the instrument cluster control module, J285 (address word 17), using the SVM action code as listed in the table below, if necessary.

Technical Service Bulletin



! Note:

To perform the update with the SD card, use ODIS Guided Fault Finding to run “SVM - Code input”. Follow the instructions outlined by the test plan. The test plan will display a prompt to insert the SD card into the MIB system. The update will be performed with the data on the SD card, and a progress meter will be displayed on the MMI screen. Note that the tester must remain hardwired to the vehicle during the update.

Model	Old Software Part Number	Old Software Version	New Software Part Number	New Software Version (or higher)	SVM Code Input
Q7	4M0920790	0262	4M0920790	0274	FPKWW274Q7
Q7	4M0920890	0262	4M0920890	0274	FPKWW274Q7
Q7	4M0920790A	0262	4M0920790A	0274	FPKWW274Q7
Q7	4M0920890A	0262	4M0920890A	0274	FPKWW274Q7

Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9025		
Damage Code:	0039		
Diagnostic Time:	GFF	0150 0000	Time stated on diagnostic protocol (Max 80 TU)
	Road test prior to service procedure	0121 0002	10 TU
	Road test after service procedure	0121 0004	10 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
Claim Comment:	As per TSB #2043734/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



Required Parts and Tools

Part Number	Part Description	Quantity
8S0906961H	SD card for software adaptation	1

Additional Information

All parts and service references provided in this TSB (2043734) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.