

LANE KEEPING FAULT MESSAGE IN THE INSTRUMENT PANEL CLUSTER (IPC) - BUILT ON OR BEFORE 17-SEP-2016**TSB 16-0167****LINCOLN:**

2017 Continental

ISSUE

Some 2017 Continental vehicles built on or before 17-Sep-2016 may exhibit a lane keeping fault message in the IPC.

ACTION

Follow the Service Procedure steps to correct the condition.

SERVICE PROCEDURE

1. Obtain the interior rear view mirror part number located on the back of the mirror.
2. Access Online Automotive Service Information System (OASIS) and select the historical vehicle bill of materials (HVBoM) tab and click rear view mirrors, glass, frames and mechanisms link.
3. Check the engineering part number for the mirror asy - rear view - inner. Does the engineering part number listed in the HVBoM match the interior rear view mirror assembly?
 - a. Yes - this article does not apply. Refer to Workshop Manual (WSM), Section 419-07 for normal diagnostics.
 - b. No - replace the interior rear view mirror assembly with the engineering part number listed in HVBoM. Refer to WSM Section 501-09.

PART NUMBER	PART NAME
GU5Z-17700-M	Interior Rear View Mirror Assembly

OPERATION	DESCRIPTION	TIME
160167A	2017 Continental: Compare The Interior Rear View Mirror Part Number To HVBoM And Replace Mirror Includes Time To Perform Programmable Module Installation And Camera Alignment (Do Not Use With Any Other Labor Operations)	0.6 Hr.

WARRANTY STATUS:

Eligible Under Provisions Of New Vehicle Limited Warranty Coverage

Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

DEALER CODING

BASIC PART NO.	CONDITION CODE
17700	38

NOTE: The information contained in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.