

SSM 46255	<p>Some 2016-2017 F-650/750 vehicles equipped with a 6.7L engine and an air brake system may exhibit inoperative cruise control and/or immediate transmission downshifting when releasing the accelerator pedal. This may be caused by an in range failure of the brake pedal pressure transducer (7920) that does not set a diagnostic trouble code (DTC). The Integrated Diagnostic System (IDS) can be used to view the WHEEL TRQ RAW PID in the generic function module (GFM). It displays the voltage value of the brake pedal pressure transducer. The voltage should be between 0.35 volts and 0.65 volts with the brakes released and will increase with brake pedal pressure. A faulty transducer will not change with brake pedal pressure. Refer to Workshop Manual (WSM), Section 206-08 for the location of the brake pedal pressure transducer.</p>
--------------	---