

01 MIL on; small EVAP leak (DTC P045600)

01 16 63 2044156/1 May 10, 2016.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
A6	2016	000001 - 111348	3.0 TFSI	

Condition

- The following DTC is stored in the engine control module, J623 (address word 01):
 - DTC P045600 (Small EVAP leak)

Technical Background

Rubber O-ring at tank filler neck is out of position.

Production Solution

Improved rubber O-ring support.

Service

- 1. Before proceeding, ensure that the gas cap was tight and that the DTC is present.
- 2. Test for a leak by first calibrating tester KLI9210 to 0.02 inch port with 14 inch/water as described on the tester. Set marker on flow meter to this position and take a picture for documentation.
- 3. Block off the filter port on the NVLD sensor (Figure 1).



Figure 1. Block the filter port on the NVLD sensor.

^{© 2016} Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

- 4. Connect the tester to the vehicle and pressurize the system (3- 5 minutes).
- 5. Take a picture of the flow meter.
- 6. Remove the purge line from the N80 valve.
- 7. Generate smoke with the smoke function of the KLI9210 tester until smoke comes out of the purge line on the N80 side.
- 8. Smoke EVAP system under pressure.
- If smoke is escaping around the filler neck of the fuel tank (wheel liner removed) replace fuel tank (Figure 2).
 - If no leak can be found, contact TAC.



Figure 2. Check for smoke escaping around the filler neck.

© 2016 Audi of America, Inc.

Page 2 of 4

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.				
Service Number:	2010				
Damage Code:	0016				
Labor Operations:	Replace fuel tank	2010 1950	160 TU		
	Rear axle remove+reinstall	4205 19XX	See Elsa		
	Brake system bleed	4701 0750	30 TU		
	Leak test and smoke EVAP system	2010 1999	20 TU		
Diagnostic Time:	GFF – Checking and clearing fault codes	0150 0000	20 TU		
	Road test after service procedure	0121 0004	10 TU		
	Technical diagnosis at dealer's discretion				
	(Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)				
Claim Comment:	As per TSB #2044156/1				

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual.* Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
4G0201060CB	Fuel Tank	1

© 2016 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Technical Service Bulletin



Additional Information

All parts and service references provided in this TSB (2044156) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

© 2016 Audi of America, Inc.

Page 4 of 4

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.