

TECHNICAL BULLETIN

JTB00515NAS1

09 SEP 2016



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 303-14

Engine MIL Illuminated With DTC P025C-11 Stored

AFFECTED VEHICLE RANGE:

XE (X760)

Model Year: 2017 Onwards
VIN: 923882 Onwards V6 S/C 3.0L Petrol
Assembly Plant: Solihull

XF (X260)

Model Year: 2016 Onwards
VIN: Y00001 Onwards V6 S/C 3.0L Petrol
Assembly Plant: Castle Bromwich

F-PACE (X761)

Model Year: 2017 Onwards
VIN: 045000 Onwards V6 S/C 3.0L Petrol
Assembly Plant: Solihull

MARKETS:

NAS

CONDITION SUMMARY:

Situation: The engine Malfunction Indicator Lamp (MIL) may be illuminated with Diagnostic Trouble Code (DTC) P025C-11 stored in the Powertrain Control Module (PCM).

Cause: This may be caused by a PCM software issue leading to the false setting of DTC P025C-11.

Action: Should a Customer express this concern, follow the Service Instruction below.

PARTS:

No Parts Required

TOOLS:



E179225

Jaguar Land Rover-approved diagnostic tool with the latest SDD software and Calibration File

Jaguar Land Rover-approved Midtronics battery power supply



E192494

WARRANTY:

⚠ **NOTE:** Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.

⚠ **NOTE:** DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Configure existing Powertrain Control Module (PCM)	86.99.26	0.2	04	T4N8046

⚠ **NOTE:** Normal Warranty procedures apply.

SERVICE INSTRUCTION:

⚠ **CAUTION:** A Jaguar Land Rover-approved Midtronics battery power supply must be connected to the vehicle battery during diagnosis / module programming.

⚠ **CAUTION:** Ensure all ignition ON/OFF requests are carried out; failure to perform these steps may cause damage to control modules in the vehicle.

⚠ **NOTE:** The Jaguar Land Rover-approved diagnostic tool must be loaded with SDD146.07 v.248 or later.

⚠ **NOTE:** Use DDW to check for Recall, Service Action, or Update Prior to Sale notice eligibility requiring a Powertrain Control Module (PCM) software update. If eligible, perform and claim the update as per that program.

1. Connect the Jaguar Land Rover-approved Midtronics battery power supply to the vehicle battery.



2. Turn ignition ON (engine not running).
3. Connect the Jaguar Land Rover-approved diagnostic tool to the vehicle and begin a new session.
4. Follow the on-screen prompts, allowing the diagnostic tool to read the VIN, identify the vehicle, and initiating the data collect sequence.
5. Select **Diagnosis** from the Session Type screen.
6. Select the **Selected Symptoms** tab and then select:
 - **Electrical - Instruments - Warning lamps - Engine malfunction lamp - Lamp illuminated**
7. Select **continue**.
8. Select the **Recommendations** tab.
9. Select **Run** to perform the '**Configure existing module - Powertrain control module**' option.
10. Follow all on-screen instructions to complete this task, ensuring all Diagnostic Trouble Codes (DTC) are cleared.
11. When all tasks are complete, select the **Session** tab and then select the **Close Session** option.
12. Disconnect the diagnostic tool and battery power supply from the vehicle.