

# Technical Service Bulletin



## 01 MIL on; small EVAP leak (DTC P045600)

01 16 74 2044156/3 August 18, 2016. Supersedes Technical Service Bulletin Group 01 number 16-72 dated August 10, 2016 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6	2016	000001 - 111348	3.0 TFSI

## Condition

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised <i>Warranty</i> (Updated Damage Code)
2	8/10/2016	Revised <i>Required Parts and Tools</i> (Added seals, bolts, and clips)
1	5/10/2016	Initial publication

- The following DTC is stored in the engine control module, J623 (address word 01):
  - **DTC P045600** (Small EVAP leak)

## Technical Background

Rubber O-ring at tank filler neck is out of position.

## Production Solution

Improved rubber O-ring support.

## Service

1. Before proceeding, ensure that the gas cap was tight and that the DTC is present.
2. Test for a leak by first calibrating tester KLI9210 to 0.02 inch port with 14 inch/water as described on the tester. Set marker on flow meter to this position and take a picture for documentation.

3. Block off the filter port on the NVLD sensor (Figure 1).



**Figure 1.** Block the filter port on the NVLD sensor.

4. Connect the tester to the vehicle and pressurize the system (3–5 minutes).
5. Take a picture of the flow meter.
6. Remove the purge line from the N80 valve.
7. Generate smoke with the smoke function of the KLI9210 tester until smoke comes out of the purge line on the N80 side.
8. Smoke EVAP system under pressure.
9.
  - If smoke is escaping around the filler neck of the fuel tank (wheel liner removed) replace fuel tank (Figure 2).
  - If no leak can be found, contact TAC.



**Figure 2.** Check for smoke escaping around the filler neck.

# Technical Service Bulletin



## Warranty

<b>Claim Type:</b>	<ul style="list-style-type: none"> <li>• 110 up to 48/50</li> <li>• G10 for CPO covered vehicles – verify owner</li> <li>• If vehicle is outside any warranty, this Technical Service Bulletin is informational only.</li> </ul>		
<b>Service Number:</b>	2010		
<b>Damage Code:</b>	0050		
<b>Labor Operations:</b>	Replace fuel tank	2010 1950	160 TU
	Rear axle remove+reinstall	4205 19XX	See Elsa
	Brake system bleed	4701 0750	30 TU
	Leak test and smoke EVAP system	2010 1999	20 TU
<b>Diagnostic Time:</b>	GFF – Checking and clearing fault codes	0150 0000	20 TU
	Road test after service procedure	0121 0004	10 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
<b>Claim Comment:</b>	As per TSB #2044156/3		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Required Parts and Tools

Part Number	Part Description	Quantity
4G0201060CB	Fuel Tank	1
N 10500802	Bolt	2
1J0919133B	Seal	1
WHT004756A	Bolt	2
WHT005800	Bolt	2
N 10772201	Clip	1
N 10719001	Bolt	6
4G0201317	Seal	1

# Technical Service Bulletin

---



## Additional Information

All parts and service references provided in this TSB (2044156) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.