



Service Bulletin

PRELIMINARY INFORMATION

Subject: Diagnostic Tip - Additional Brake Pedal Effort

Models: 2015-2016 Cadillac Escalade Models
2014 Chevrolet Silverado 1500
2015-2016 Chevrolet Silverado 1500, Suburban, Tahoe
2014 GMC Sierra 1500
2015-2016 GMC Sierra 1500, Yukon Models

This PI was superseded to add 2016 Models and update Recommendation. Please discard PIT5361.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

In some rare situations, a customer may comment on a hard brake pedal or that increased effort is needed to depress the brake pedal. While performing normal diagnostics, fluid may be found in the brake booster and/or the booster vacuum line.

Important: Pay close attention to the fluid and if it is determined to be engine oil, it could be coming from the vacuum pump. The vacuum pump is belt-driven and mounted to the side of the engine block. It is lubricated by pressurized engine oil.

Recommendation/Instructions

If engine oil is found, it is important the following parts are replaced. If not, the condition will return.

1. Vacuum Pump
2. Vacuum Line between the booster and the pump
3. Brake Booster
4. Master Cylinder
5. Vacuum Pump Belt

Parts Information

Part Number	Description	Qty
12669488	PUMP ASM-VAC	1
23144638 (VYU) or 23135228 (w/o VYU)	PIPE ASM-P/B BOOS VAC	1
23135220	BOOSTER ASM-P/B	1
20925765	CYLINDER-BRK MAS	1
12658179	BELT - VAC PUMP	1

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2480118 *	Replace vacuum pump, belt, vacuum pump to booster hose, vacuum brake booster, and brake master cylinder	2.8 hr
* This is a unique labor operation for bulletin use only.		

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION