

# TECHNICAL BULLETIN

## Q603NAS1

15 AUG 2016



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

### ***SECTION: 206-05***

### **Service Action: Electronic Park Brake Module**

#### **AFFECTED VEHICLE RANGE:**

##### **Range Rover Sport (LW)**

**Model Year:** 2016  
**VIN:** 571452-584863  
**Assembly Plant:** Solihull

##### **Range Rover Sport (LW)**

**Model Year:** 2016  
**VIN:** 644695-651468  
**Assembly Plant:** Solihull

##### **Range Rover (LG)**

**Model Year:** 2016  
**VIN:** 274001-285028  
**Assembly Plant:** Solihull

MARKETS:

NAS

#### **CONDITION SUMMARY:**

**Situation:** An issue has been identified on a limited number of vehicles within the listed Affected Vehicle Range which may have been manufactured away from process and in some cases, a yellow warning light may be illuminated on the instrument cluster with the warning 'Electronic Park Brake Fault'.

In these circumstances, there is no performance issue associated with the operation of the Electric Park Brake but the warning indicator will cause concern and customer dissatisfaction until the required remedial work has been completed.

**Action:** Retailers are required to **HOLD** affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the Service Instruction detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but **must** have it completed prior to vehicle handover to the customer. Affected vehicles already in the hands of customers should be updated at the next available opportunity.

#### **PARTS:**



**NOTE: Order only the expected percentage demand of parts identified.**

DESCRIPTION	PART No./SUNDRY CODE	QTY./VALUE	EXPECTED % of VEHICLES REQUIRING PARTS
Electronic Park Brake Module	LR070636	1	100

#### **SPECIAL TOOLS:**

Refer to Workshop Manual/Service Instruction for any required special tools

## **WARRANTY:**



**NOTE: Check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action.**

At the time of confirming a booking for vehicle repair, ensure that **all** outstanding Recalls and Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code **Q603** together with the relevant Option Code from the table. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **31 July 2018** closure date must be submitted or payment within 30 calendar days of completion of the repair.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS/SUNDRY CODE	QTY./VALUE
Q603	B	Renew Electronic Park Brake Module	70.35.49	0.30 - Range Rover Sport (L494) 0.20 - Range Rover (L405)	LR070636	1
Q603	C	Renew Electronic Park Brake Module Drive in/drive out	70.35.49 02.02.02	0.30 - Range Rover Sport (L494) 0.20 - Range Rover (L405) 0.20	LR070636 -	1 -

Normal Warranty policies and procedures apply.

## **SERVICE INSTRUCTION:**

1. Replace the Electric Park Brake Control Module (EPBCM) (see TOPIx Workshop Manual section 206-05: Parking Brake and Actuation - Parking Brake Module).