

# Service Bulletin

16-020

**February 26, 2016** 03231 Version 1

## **Product Update: Monroney Label (Hawaii Only)**

#### **AFFECTED VEHICLES**

Year	Model	Trim	VIN Range		
2014–16	Accord	ALL Check the iN VIN status for eligibility			
2014–16	Civic	ALL	Check the iN VIN status for eligibility		
2014–16	CR-Z	ALL	Check the iN VIN status for eligibility		
2015–16	Fit	ALL	Check the iN VIN status for eligibility		
2014	Insight	ALL	Check the iN VIN status for eligibility		

#### **BACKGROUND**

On the Monroney label, the bumper compliance statement is missing.

Do an iN VIN status inquiry to make sure the vehicle is shown as eligible.

Vehicles affected by this campaign may be in your new vehicle inventory. Repair these vehicles before they are sold. No action is needed on vehicles that have been sold.

#### **CORRECTIVE ACTION**

Attach the Monroney update label to the window area next to the Monroney label.

### **PARTS INFORMATION**

Part Name	Part Number	Quantity
Accord Monroney Update Label (Hawaii Only)	Y1073A	1
Civic Monroney Update Label (Hawaii Only)	Y1073B	1
CR-Z Monroney Update Label (Hawaii Only)	Y1073D	1
Fit Monroney Update Label (Hawaii Only)	Y1073D	1
Insight Monroney Update Label (Hawaii Only)	Y1073D	1

Extra labels are not available through the normal parts ordering process. Contact Helm Inc. at 800-782-4356, and use the applicable reorder number.

#### WARRANTY CLAIM INFORMATION

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
8290A2	Attach the Monroney update label.	0.2 hr	6AH00	JX700	16-020A	73450-TBA-A00

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.

## **REPAIR PROCEDURE**

Make sure the inside window area is clean, dry, and at room temperature. Attach the Monroney update label in the position shown.

NOTE: If necessary, bring the vehicle inside to warm up to room temperature; otherwise the label may not stick to the glass.



**END**