

TECHNICAL BULLETIN

LTB00888NAS1
13 JAN 2016



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 501-12

'Creak' / 'Tizz' Noise From Instrument Panel Center Vent

AFFECTED VEHICLE RANGE:

Discovery Sport (LC)

Model Year: 2015

VIN: 500429-544945

Assembly Plant: Halewood

MARKETS:

NAS

CONDITION SUMMARY:

Situation: A 'creak' / 'tizz' noise may be evident from the instrument panel center console center stack and the navigation unit.

Cause: This may be caused by incompatible materials installed at the mating surfaces.

Action: Should a customer express this concern, follow the Service Instruction below.

PARTS:

No Parts Required

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:

 **NOTE:** Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.


 **NOTE:** DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Ventilator - Face level - Inner - Pair - Renew	80.15.21	1.10	42	LR072476


 **NOTE:** Normal Warranty procedures apply.

COMPONENT LOCATION


1Component location.

**SERVICE INSTRUCTION:**

- 1 Remove the climate control unit (see TOPIX Workshop Manual, section 412-01: Climate Control).
- 2 Remove the instrument panel center vent.



- 3 Apply anti-squeak tape from the Squeaks & Rattles kit to the areas where the center vent contacts the navigation unit.



E187298

4 Anti-squeak tape applied.




E187299

5  NOTE: left-side shown; right-side similar.


Apply anti-squeak tape to the instrument panel center vent at the contact point with the navigation unit.

- Anti-squeak tape must be applied to both sides of the instrument panel center vent.




6 Install the instrument panel center vent.

- Torque:
 - Screws: 6Nm
 - M6 bolts: 10Nm



7 Apply anti-squeak tape to the instrument panel center vent at the contact point with the climate control unit.

- The anti-squeak tape must cover the entire height of the climate control unit enclosure.



8 Install the climate control unit (see TOPIx Workshop Manual, section 412-01: Climate Control).