

LTB00927NAS2

TECHNICAL BULLETIN

21 MAR 2017



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

This reissue replaces all previous versions. Please destroy all previous versions.

SECTION:

418-00

SUBJECT/CONCERN:

Parking Aid System Rear Harness Corrosion

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
Discovery Sport (LC)	2015-2017	500429-640975	Halewood

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:**SITUATION:**

The Parking Aid system may be inoperative.

CAUSE:

This may be caused by a rear fog lamp that has cracked and water ingress into the harness corroding the Park Aid system harness, causing failure.

ACTION:

Should a customer express this concern, follow the Service Instruction below.

PARTS:

PART NUMBER	DESCRIPTION	QUANTITY:
LR060911	Lamp - Rear fog - LH	1
LR060910	Lamp - Rear fog - RH	1
LR074179	Harness - Parking aid sensors - With: powered tailgate, rear parking aid - Without: perpendicular parking	1

PART NUMBER	DESCRIPTION	QUANTITY:
LR074180	Harness - Parking aid sensors - With: powered tailgate, rear parking aid, perpendicular parking	1
LR074182	Harness - Parking aid sensors - With: hands-free tailgate, rear parking aid - Without: perpendicular parking	1
LR074183	Harness - Parking aid sensors - With: hands-free tailgate, rear parking aid, perpendicular parking	1
LR076288	Harness - Parking aid sensors - With: rear parking aid - Without: perpendicular parking	1
LR076289	Harness - Parking aid sensors - With: rear parking aid, perpendicular parking	1

WARRANTY:

NOTES:

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.
- DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Lamp assembly - Rear fog guard - One side - Renew	86.41.15	1.3	D8	LR060911
Lamp assembly - Rear fog guard - Pair - Renew	86.41.10	1.4	D8	LR060911
Wiring harness - Parking aid sensors - Renew	86.54.17	1.7	D8	LR060911


NOTE:

Normal Warranty procedures apply.

SERVICE INSTRUCTION:

NOTE:

The Parking Aid system may also be referred to a Park Distance Control.





Inspect the rear left and right fog lamps for cracking and water ingress.

- If no fault is found with the fog lamp(s), this is not the cause of the fault.
- If the fog lamp(s) is found to be cracked or has water ingress, go to Step 2.

-
- 2 Remove the rear bumper cover (see TOPIx Workshop Manual section 501-19: Bumpers - Rear Bumper Cover).
-

3



E189513

Inspect the Parking Aid system wiring harness for damage and/or corrosion.

- If the Parking Aid system wiring harness is not damaged or corroded, go to Step 5.
- If the Parking Aid system wiring harness is damaged or corroded, go to Step 4.

4 Renew the Parking Aid system wiring harness (see TOPIx Workshop Manual section 501-19: Bumpers - Rear Bumper Cover - Steps 15 and 16).

5 Renew the defective fog lamp(s) (see TOPIx Workshop Manual section 417-01: Exterior Lighting - Rear Fog Lamp).

6 Install the rear bumper cover (see TOPIx Workshop Manual section 501-19: Bumpers - Rear Bumper Cover).