

[Next Unread Message](#)[View Message](#)

Sent on	02	03	2017	Expires on	02	17	2017
---------	----	----	------	------------	----	----	------

From	Parts and Service Division
------	----------------------------

Subject	Request for Info: 2016 2-Door Civic High Mount Stop Light Cover Issue
---------	---

PRIORITY/ACTION REQUIRED

To: All Honda Service Managers/Advisors
 From: Technical Research & Support Group
 RE: Request for Info: 2016 2-Door Civic High Mount Stop Light Cover Issue

**This message is solely directed to Honda dealership personnel; please handle accordingly.
 Print this i/N message and provide a copy to the Shop Foreman and all Service Advisors.**

Background

American Honda (AHM) is investigating certain 2016 2-Door Civics with a customer complaint of the high mount stop light cover detaching or falling down. To fully understand the cause of this condition, AHM would like to collect specific information from the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirement:

1. LX & LX-P (Non-Turbo) VIN must be between 2HGFC4...GH309980 & 2HGFC4...GH315290.
2. EX-T, EX-L & Touring (Turbo) VIN must be between 2HGFC3...357197 & 2HGFC3...GH360273.
3. Please note that the above VIN range is not a part of the Service Bulletin 16-099.
4. No repair has been attempted for this issue.

Action Required

If you have or know of such a vehicle, please call the Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.