

QUARANTINE NOTICE

Reference number:	QN-15-0047V2	Issued: 08 March 2017
Subject:	AMi III Apple CarPlay	
Model(s):	All 17MY and 17.5MY vehicles but not DB11	
VIN Range:	Refer to the separately published Vehicle Identification Number (VIN) list	
Applicable to:	All Dealers	
Distribute to:	After Sales Manager Executive Manager Service Manager Sales Manager	Warranty Staff Technician(s) Parts Staff

Note: *This repair is the same as Service Action SA-15-0267V2. Use this Quarantine Notice for vehicles that are not registered and have not been given to a Customer.*

Some vehicles in the affected VIN list for this Quarantine may now be registered and given to a Customer. Make sure that you do a check of the Online Dealer Warranty (ODW) database to make sure that all necessary work is done to every vehicle.

Reason for Version 2 of this Service Action (QN-15-0047V2).

We have issued Version 2 of this Quarantine Notice because we have included a note that tells you to make sure that you have already updated the infotainment system according to the Technician's Notice published in Week 45 of last year. Changes to this document have a black line against them in the left margin. Please destroy all copies of QN-15-0047 that you have and replace them with this Quarantine Notice QN-15-0047V2.

Reason for this Quarantine Notice (QN-15-0047)

The software is now available to let you install the Apple CarPlay feature on all 17 and 17.5MY Aston Martin vehicles. The software will be sent to a pre-designated person in your After Sales department – in a single file of 90 MB – via MX, the data exchange service of Majenta Solutions. The file will be sent on Monday 6 March. Please make sure that the pre-designated person in your After Sales department has activated their MX account and that they have followed the instructions sent to them.

This software will update – in one procedure – all the parts of the AMi III infotainment system – base software, application software and the Bluetooth software on the System Information Page of the infotainment system.

The software update will also install BT SMS Message Center. It will improve stability and correct bugs which we know about in the installed software.

Note: *CarPlay™ is a trademark of Apple Inc., registered in the U.S. and other countries. The Bluetooth® word mark and logos are registered trademarks owned by Bluetooth SIG, Inc., and any use of such marks by Aston Martin Lagonda Ltd. is under license.*

Workshop Procedure

CAUTION: IT IS VERY IMPORTANT THAT THE INFOTAINMENT SYSTEM IS UP-TO-DATE BEFORE YOU DO THIS PROCEDURE.

MAKE SURE THAT YOU HAVE INSTALLED THE AMI III SOFTWARE UPDATE INCLUDED IN THE FILE AML_MY17_1045X226_251016_MASTER_RO.UPDATE THAT IS AVAILABLE TO DOWNLOAD FROM DCS.

REFER TO [HTTP://DCS.ASTONMARTIN.COM/AFTER-SALES/TECHNICIAN-NOTICES](http://DCS.ASTONMARTIN.COM/AFTER-SALES/TECHNICIAN-NOTICES), WEEK 16/45 "INCORRECT TIME DISPLAY".

CAUTION: IT IS VERY IMPORTANT THAT YOU DO THIS PROCEDURE STEP-BY-STEP OR THE INFOTAINMENT SYSTEM WILL NOT OPERATE CORRECTLY.

Note: *This software update will erase all personal preferences and settings that have been stored and it will return the infotainment system to the default factory state.*

You must erase the vehicle from the paired devices list of a mobile phone, tablet or other device that has been paired to the infotainment system.

You must then do the Bluetooth pairing procedure again to pair the device again to the infotainment system. Refer to the Bluetooth pairing instructions in the Owners Guide of the vehicle.

CAUTION: YOU MUST CONNECT A BATTERY CHARGER TO THE BATTERY OF THE VEHICLE ON WHICH YOU DO THIS PROCEDURE. IF THE VEHICLE BATTERY DISCHARGES DURING THE PROCEDURE, THE SOFTWARE UPDATE WILL FAIL AND THIS WILL CAUSE DAMAGE TO THE MODULE.

1. Log in to your MX account and download the file **AML_MY17_1053x231_010317_MASTER_RO.update** that Aston Martin have sent you.
2. Get a USB stick that contains no other files. Copy the file on to the USB stick.

Note: *If you are also installing the software included in the AML_MY17_1045x226_251016_MASTER_RO.update file, you must do this procedure separately and you must use a different USB stick for this software.*

Note: *The software installation does not erase the file at the end of this procedure. The USB stick can be used again.*

3. Set the ignition to On.
4. Open the armrest storage tray or cubby box to show the USB port.
5. Connect the USB stick to the USB port.

CAUTION: DO NOT REMOVE THE USB STICK FROM THE PORT DURING THE UPDATE PROCEDURE.

6. The infotainment system will recognise the USB stick as a USB storage device that contains an update file. The display screen will freeze and go black. A text message related to the update will display.
7. The update procedure will start automatically. The procedure will continue for two and half minutes and will restart the Infotainment Control Unit twice.
8. The automatic update procedure is complete when the infotainment system has started again and displays the main menu. You will now be able to see the CarPlay icon.

9. Set the ignition to Off.
10. Get out of the vehicle and lock it.
11. Wait for a minimum of two minutes. The Infotainment Control Unit will go into full sleep.
12. Unlock the vehicle.
13. Set the ignition to On.
14. Use the joystick to navigate to the System Information page. The page will display the updated Part Numbers for the App and for the Base (refer to Figure 1).




Figure 1

Note: *The personal preferences and settings that were stored in the infotainment system must be put back in.*

You must then do the Bluetooth pairing procedure again to pair the applicable mobile phone, tablet or other device again to the infotainment system. Refer to the Bluetooth pairing instructions in the Owners Guide of the vehicle.

Warranty Data

Procedure and Labour Time

Description	Labour Time
AMi III Apple CarPlay Software Update.	0.2 hours

Please Note:

When you have completed this Service Action, make sure that you make an entry in Section A of the Vehicle Owner's Guide to show that the procedure is completed.

If you have any questions related to this Quarantine Notice, please contact: Aston Martin Technical Services on: +44 (0) 1926 644720, email: askamtech@astonmartin.com,
Or contact your After Sales Manager.

The English version of this Quarantine Notice is written in
Simplified Technical English to ASD-STE100™.