

**Date:** April 5, 2017

# SERVICE BULLETIN

**Service Bulletin No.:** 2017-0013

**Product Models Affected:**

- AeroElite Ford 270 MY2010 – MY2016
- AeroElite Ford 290 MY2010 – MY2016
- AeroElite Ford 300 MY2010 – MY2016
- AeroElite Ford 320 MY2010 – MY2016

FORM Rev 2017-0323

**Purpose:**

To repair cracks in the cab outer skin sheet metal.

**Tool(s) / Equipment Required:**

- |                       |                                 |
|-----------------------|---------------------------------|
| Drill                 |                                 |
| Wire brush            | Rubber Gloves (PPE)             |
| Sanding disc          | Dust Mask (PPE)                 |
| Sanding block         | Safety Glasses (PPE)            |
| Standard wrench set   | Hearing Protection (PPE)        |
| Flat tip screw driver | Weld - Leathers & Gloves (PPE)  |
| Grout removal tool    | Weld - Helmet/Face Shield (PPE) |
| Grinding Wheel        | Drill Bits                      |
| Welder                |                                 |

**Part(s) / Material Required:**

<u>Description</u>	<u>Part Number</u>	<u>Quantity</u>
Isopropyl alcohol	N/A	A/R
Corrosion inhibitor paint	N/A	1 can
Sand paper, 220 – 600 grit	N/A	A/R
3M Automix Panel Bonding Adhesive 8115	N/A	1 cartridge
Automotive body filler	N/A	1 can
Windshield seal		1
Kit, Repair F550 A-Pillar	CS0000103	1
6" X 9" notched 18GA sheet steel	00389831	
4" x 12" 18GA sheet steel ASTM A-569	00389811	
Sika-flex 252	E52631	1

**Procedure:**

If an exterior sheet metal crack has been identified above the windshield, follow the procedure below to repair the crack.

**Prep Instructions for access to cracked area.**

**Step 1:** Carefully remove the OEM windshield seal and the undamaged windshield, setting aside the undamaged windshield for re-installation after the sheet metal is repaired.

**Step 2:** Scrape away or pull away dried sealant above the windshield area without damaging the fiberglass roof cap any further. Reference Figure 1.

**Note:** The cracked area between the OEM cab area and the fiberglass cap will need to be accessed by scraping away the sealant.

**Step 3:** From inside, remove the headliner to have a visual inspection of any wiring harnesses that will need to be moved so they are not damaged.



Figure 1 The area inside the red box will need sealant removed.

**Apply the Support Plate:**

**Step 1:** Apply the support plate, 0038981 (4" X 12" sheet steel) Figure 2 included for reference, by first inserting into the area above the roof and below the fiberglass front cap, in the area where the sealant was removed.

**Step 2:** Mark the plate along the edge of the windshield opening. Remove and cut the plate to size.



Figure 2 Support Plate 0038981.

## Outer skin repair:

**Step 1:** Sand the area where the sealant was removed to a smooth finish using the sanding block and sandpaper.

**Step 2:** Wash the surface with soap and water to remove water soluble contaminants.

**Step 3:** Remove all debris and loose particles and clean the area with isopropyl alcohol.

**Step 4:** Set previously trimmed plate in place and carefully stitch weld the entire outer edge to the OEM sheet steel. Allow the welds to completely cool before moving on.

**Step 5:** Grind welds smooth.

**Step 6:** Apply automotive body filler around the edges of the plate and sand smooth to complete the installation of the exterior plate.

## Interior Skin Repair:

**Step 1:** Remove the farthest left fastener over the windshield opening and the farthest forward fastener between the A-pillar and B-pillar (over the driver's door opening). Figure 3 represents both fasteners that need removed.

**Step 2:** Apply a thin film of 3M Automix Panel Bonding Adhesive 8115 to the top side of the interior skin repair plate, 0038983.

**Step 3:** Install the plate above the existing plywood, against the inside of the OEM exterior sheet metal.

**Step 4:** Drill out the holes for the hardware that was previously removed.

**Step 5:** Reinstall the hardware and torque to 8 ft.-lbs.

Allow 24 hours to dry at a minimum of 70°Fahrenheit.

**Note: Do not apply 3M Automix Bonding Adhesive above 90° Fahrenheit.**



Figure 3 Roof reinforcement area with nuts that need removed.




Figure 4 Representation of 0038983

## **Ready the front cap for paint**

**Step 1:** The affected area of the fiberglass cap will need to be stripped and sanded before a primer is applied for painting. Using 320- grit sandpaper, remove any waxy residue or finish from the surface.

**Step 2:** Once the surface has the waxy residue removed, roughen the panel so the primer and the top paint can grip the surface. Use 120-grit sandpaper to roughen the surface.

**Step 3:** Apply a fiberglass primer to the surface of the material and allow to dry. Apply two additional coats and allow to dry.

**Step 4:** Paint area with desired color.

## **Finish the repair process:**

**Step 1:** Reinstall original windshield with new windshield seal.

**Step 2:** Clean the exterior surface with soap and water and dry.

**Step 3:** Clean the exterior area with isopropyl alcohol.

**Step 4:** Apply sika flex over the repaired area between the sheet steel and fiberglass.

**Step 5:** Allow the sika-flex to dry at least 24 hours.

**Step 6:** Replace wiring harnesses back into original position.

**Step 7:** Replace the cab liner pad.



**Figure 5** Finished cap included for reference.

## **Contact Information:**

EIDorado Customer Service, 1655 Wall Street, Salina, KS 67401; or by calling (785) 827-1033 / (800) 955-9086; or by Email: [bussupport@eldorado-bus.com](mailto:bussupport@eldorado-bus.com); or by Fax: (785) 827-3017.

The repair time estimate is 6 hours, not including dry time.