

Technical Service Bulletin

	GROUP	NUMBER
	CAMPAIGN	17-01-019
•	DATE	MODEL(S)
	FEBRUARY 2017	VELOSTER,
		ACCENT

SUBJECT:

PURGE CONTROL SOLENOID VALVE (PCSV) DTC P0441 ECM UPDATE (SERVICE CAMPAIGN T1T)



* IMPORTANT

****** Retail Vehicles ******

Dealers must perform this Service Campaign on all affected vehicles whenever an affected vehicle is in the shop for any maintenance or repair.

When a vehicle arrives at the Service Department, access Hyundai Motor America's "Warranty Vehicle Information" screen via WEBDCS to identify open Campaigns.

Description:

This bulletin provides information related to ECM (Engine Control Module) software update for diagnostic trouble code (DTC) P0441 - Canister Purge Valve (CPV) - Incorrect CPV Flow. There is no vehicle performance concern associated with this condition.

Applicable Vehicle: Certain 2016MY Veloster(FS) and Accent(RB) with 1.6L GDI engines

GDS Information:

System Selection: ENGINE (ECM)		
Event #	Description	
428*	FS 1.6GDI PCSV MIL LAMP ON(P0441) IMPROVEMENT	
429*	RB 1.6GDI PCSV MIL LAMP ON(P0441) IMPROVEMENT	

(*or use a later available event as listed in the GDS ECU Update screen if one is available.)

Warranty Information:

Model	Op Code	Operation	Op Time	Causal Part	Nature Code	Causal Code
Veloster (FS) Accent (RB)	60C127R0	ECM UPDATE	0.3 M/H	Use applicable ECM P/N from ROM ID table	I3A	ZZ3

NOTE: Submit claim using the Campaign Claim Entry Screen.

NOTICE

You must initially perform GDS ECU Update in Auto Mode.

• If the ECU Update starts but then fails in Auto Mode, perform the update in Manual Mode to recover.

Circulate To: Service Manager, Warranty Manager, Service Advisors, Technicians, Fleet Repair



GDS Vehicle Battery Voltage Warning:

If voltage is below 12 volts as per the below GDS warning, then select **Back** and run the engine at least 20 minutes to ensure an adequate battery state of charge for reliable update results. Turn ignition back on, and then retry the ECU update again.



Service Procedure:

- 1. Perform GDS software update:
 - Refer to TSB 15-GI-001 for the tablet-based Mobile GDS ECU update procedures.
 - Refer to TSB **15-GI-002** for the PC-based GDS ECU update procedures.
- 2. Check for Diagnostic Trouble Codes in the ALL menus and erase any DTC.
- 3. Erase the DTC in the BlueLink system according to TSB 12-BE-005-2.
- 4. Confirm normal vehicle operation.

ROM ID Information Table:

Veloster (FS): (NOTE: IMMO (YES) = Start Stop Button, IMMO (NO) = Key Start)

TM	IMMO. ECU P/No.		ROM ID		
1 141	IIVIIVIO.	LCO F/NO.	OLD	NEW	
	NO	39125-2BFK5	GGFS-GFU6ES00H00	GGFS-GFU6ES02H00	
DCT	10	39123-2DI N3	GGFS-GFU6ES01H00	GGF3-GF00E302F100	
DCI	YES	39125-2BFK0	GGFS-GFU6FS00H00	GGFS-GFU6FS02H00	
	163	39125-2DFN0	GGFS-GFU6FS01H00	GGF3-GF00F302F100	
	NO 39121-2BI	39121-2BFK5	GGFS-GFU6ES00600	GGFS-GFU6ES02600	
MT	NO	NO 39121-26FK5	GGFS-GFU6ES01600	GGF3-GF06E302600	
IVII	YES	39121-2BFK0	GGFS-GFU6FS00600	GGFS-GFU6FS02600	
	IES	29 12 1-2 BFKU	GGFS-GFU6FS01600	GGF3-GF06F302600	

Accent (RB): (NOTE: IMMO (YES) = Start Stop Button, IMMO (NO) = Key Start)

TM	IMMO.	ECU P/No.	ROM ID	
I IVI	IIVIIVIO.	ECO P/NO.	OLD	NEW
		39110-2BRG2	GGRB-GNU6ES00600	
MT	NO	391B1-2BRG2	GGRB-GNU6ES01600	GGRB-GNU6ES02600
			GGRB-GNU6ES02600	
AT	МО	39110-2BRG7	GGRB-GNU6PS00C00	GGRB-GNU6PS02C00
Al	NO	391B1-2BRG7	GGRB-GNU6PS01C00	GGRB-GINU6P502C00

TSB #: 17-01-019 Page 2 of 3

Manual Mode Password Information Table:

Veloster(FS): NOTE: +IMMO = Start Stop Button, -IMMO = Key Start

MENU	PASSWORD
FS 1.6GDI DCT -IMMO 39125-2BFK5	2525
FS 1.6GDI MT -IMMO 39121-2BFK5	2125
FS 1.6GDI DCT +IMMO 39125-2BFK0	2520
FS 1.6GDI MT +IMMO 39121-2BFK0	2120

Accent(RB): NOTE: -IMMO = Key Start

MENU	PASSWORD
RB 1.6GDI MT -IMMO 39110/B1-2BRG2	1122
RB 1.6GDI AT -IMMO 39110/B1-2BRG7	1127

TSB #: 17-01-019 Page 3 of 3