



# Preliminary Information

PIT5546 Dead Battery / P1682 / Crank No Start / Unable To Program ECM / Headlamp Water Intrusion / Engine Runs With Ignition Off

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500	2016 - 2017	All	All	All	All
GMC	Sierra 1500	2016 - 2017	All	All	All	All
Involved Region or Country	North America					
Condition	<p>Some customers may comment on any of the following;</p> <ul style="list-style-type: none"><li>- no crank</li><li>- dead battery</li><li>- crank no start</li><li>- Unable to SPS program ECM</li><li>- DTC P1682 or P129D</li><li>- Engine stays running with ignition off</li></ul> <p>While performing normal diagnostics, voltage may be found on any one of the following underhood electrical center fuses with the ignition off: F26UA, F31UA, F34UA, F39UA, F40UA, and F56UA. These fuses are switched ignition and should not have any voltage with the ignition off. This can cause multiple modules to stay awake and never go to sleep causing a dead battery. These concerns can be intermittent and may be more apparent during wet weather conditions.</p>					
Cause	Water intrusion into either of the headlamp assemblies or the headlamp assembly connections can cause any one of the above conditions.					

**Correction:**  
Inspect each headlamp assembly for water intrusion. If water intrusion is found, disconnect the appropriate headlamp assembly and evaluate the condition. If condition is alleviated, replace headlamp assembly as necessary. If disconnecting the headlamp assembly does not alleviate the condition, check for water intrusion in the headlamp assembly connections and repair as necessary.

Version History

Version	1
Modified	