Date: Apr-2017



Service Bulletin

TECHNICAL

Subject: **Rattle or Flutter Noise from Side Door**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Trax (1st Position of VIN – 3)	2017	2017			All	All


Involved Region or Country	North America
Condition	Some customers may comment on hearing a rattle or flutter noise coming from a side door.
Cause	The cause of the condition may be wind passing through the door catching a loose segment of the door water deflector, causing it to rattle/flutter.
Correction	Remove the door trim panel and reinstall the water deflector, as necessary, on the affected door.

Warranty Information


For vehicles repaired under warranty:

Labor Operation	Description	Labor Time			
1480788*	Re-secure Side Door Water Deflector (Front or Rear)	0.3 hr			
*This is a unique Labor Operation for Bulletin use only.					

Service Procedure



1. Remove the trim panel on the affected door. Refer to the appropriate Front or Rear Side Door Trim Replacement (Chevrolet) in SI.



- 2. Inspect the door water deflector for any areas (1) where the deflector may have pulled loose from the door sheet metal. Re-secure the deflector.
- 3. Reinstall the door trim panel. Refer to the appropriate Front or Rear Side Door Trim Replacement (Chevrolet) in SI.

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safety. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION