

[Next Unread Message](#)[View Message](#)

Sent on	07	12	2017	Expires on	07	26	2017
----------------	----	----	------	-------------------	----	----	------

From	Parts and Service Division
-------------	----------------------------

Subject	** Inspection Request ** 2018 Odyssey - Door Lock Cables & RES Display
----------------	--

Message **PRIORITY/ACTION REQUIRED**

To: All Honda Service, Sales, & Parts Managers
From: Technical Research & Support (TRS)
Re: **** Inspection Request ** 2018 Odyssey – Door Lock Cables & RES Display**

If you receive this *i/N* message, you may have and/ or be receiving the vehicles that are affected by this request. Please check to see if you have VINs on the list

Background

American Honda (AHM) has discovered certain 2018 Odysseys with a possible door lock cable routing and/or a RES display concerns. AHM requests that you inspect and repair these vehicles prior to sale.

Affected VINs List:

VINs are listed by dealer# with which inspection(s) the vehicle may need.

Click [here](#) to view affected VINs.

Inspection and Repair Procedure:

Click [here](#) to view the inspection procedure (Door Lock Cable)

Click [here](#) to view the inspection procedure (RES Display)

Click [here](#) to view No Good Serial Numbers (Gray)

Click [here](#) to view No Good Serial Numbers (Beige)

Action Required:

Once you complete the inspections, please contact Ms. Maria Higuera at Technical Research & Support (TRS) Group at 1-800-880-1072 with inspection results for further instructions and warranty information.

If the vehicle has been dealer traded or sold to a retail customer, please contact Maria immediately.

Thank you.

