



TECHNICAL SERVICE BULLETIN

3.5L GTDI - Illuminated Malfunction Indicator Lamp (MIL) - DTC P2195, P2197, P2626 And/Or P2629

17-2124

11 July 2017

This bulletin supersedes TSB 17-2079. Reason for update: To update the Parts List.

Model:

Ford
2015-2017 Explorer
2015-2016 F-150

Issue: Some 2015-2017 Explorer and 2015-2016 F-150 vehicles, equipped with 3.5L Gasoline Turbocharged Direct Injection (GTDI) engines may exhibit an illuminated MIL with diagnostic trouble codes (DTCs) P2195, P2197, P2626 and/or P2629 stored in powertrain control module (PCM) memory.

Action: Follow the Service Procedure steps to correct the condition.

Parts

Part Number	Description	Quantity
8F9Z- 9F472-H	Heated Oxygen Sensor - Explorer (Left/Right Side), F-150 (Right Side)	2
8F9Z-9F472-G	Heated Oxygen Sensor - F-150 (Left Side)	1

Warranty Status: Eligible Under Provisions Of New Vehicle Limited Warranty Coverage And Emissions Warranty Coverage Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

Description	Operation No.	Time
2015-2017 Explorer 3.5L GTDI: Retrieve DTCs And Replace The Right Side Heated Oxygen Sensor (Do Not Use With Any Other Labor Operations)	172124A	0.7 Hr.
2015-2017 Explorer 3.5L GTDI: Retrieve DTCs And Replace The Left Side Heated Oxygen Sensor (Do Not Use With Any Other Labor Operations)	172124B	0.6 Hr.
2015-2017 Explorer 3.5L GTDI: Retrieve DTCs And Replace Both The Right And Left Side Heated Oxygen Sensor (Do Not Use With Any Other Labor Operations)	172124C	0.8 Hr.
2015-2016 F-150 3.5L GTDI: Retrieve DTCs And Replace The Right Side Heated Oxygen Sensor (Do Not Use With Any Other Labor Operations)	172124D	0.5 Hr.
2015-2016 F-150 3.5L GTDI: Retrieve DTCs And Replace The Left Side Heated Oxygen Sensor (Do Not Use With Any Other Labor Operations)	172124E	0.6 Hr.
2015-2016 F-150 3.5L GTDI: Retrieve DTCs And Replace Both The Right And Left Side Heated Oxygen Sensors (Do Not Use With Any Other Labor Operations)	172124F	0.8 Hr.

Repair/Claim Coding

Causal Part:	9F472
Condition Code:	49

Service Procedure

1. Connect the Ford Integrated Diagnostic System (IDS) service tool or equivalent scan tool to the data link connector (DLC). Check for DTCs. Is DTC P2195, P2197, P2626 and/or P2629 stored in the PCM memory?

(1). Yes - replace the affected heated oxygen sensor (HO2S). Refer to Workshop Manual (WSM), Section 303-14.

- DTC P2195/P2626 - bank 1 sensor 1 HO2S (Right Side)
- DTC P2197/P2629 - bank 2 sensor 1 HO2S (Left Side)

(2). No - this article does not apply. Refer to Powertrain Control/Emissions Diagnosis (PC/ED) Manual for normal diagnostics.

© 2017 Ford Motor Company

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.