

Q663 UPS10016-2BNAS1

TECHNICAL BULLETIN

03 FEB 2017



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

SECTION:

414-01

SUBJECT/CONCERN:

Update Prior to Sale: Negative Battery Cable Connection

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:	APPLICABILITY:
Range Rover Sport (LW)	2017	666892-670469	Solihull	Vehicles Without: 7 Seats

MARKETS:

NAS

CONDITION SUMMARY:

SITUATION:

An issue has been identified on certain vehicles within the listed Affected Vehicle Range where the negative battery cable connection is under torqued.

ACTION:

Retailers are required to **HOLD** affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the Service Instruction detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but **must** have it completed prior to vehicle handover to the customer.

This program does not apply to any vehicle already registered and in use, either with the retailer or customer. Any vehicle already in use may continue to be driven and any repair instructions deemed necessary will be communicated through a separate Field Action or Technical Bulletin.

PARTS:

No parts required.

SPECIAL TOOLS:

Refer to Workshop Manual/Service Instruction for any required special tools.

WARRANTY:



NOTE:

Check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action.

At the time of confirming a booking for vehicle repair, ensure that **all** outstanding Recalls and Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting the Program Code together with the relevant Option Code. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **23 June 2017** closure date must be submitted or payment within 30 calendar days of completion of the repair.

**NOTE:**

**'Vehicles without 7 seats' may also be referred to as
'Vehicles Without Occasional Rear Seats'.**

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS /SUNDRY CODE	QTY. /VALU
Q663	B	Battery Negative Terminal Nut - Repair - Vehicles Without Occasional Rear Seats	86.15.25	0.2	-	-
Q663	C	Battery Negative Terminal Nut - Repair - Vehicles Without Occasional Rear Seats Drive in/drive out	86.15.25 02.02.02	0.2 0.2	- -	- -
Q663	F	Battery Negative Terminal Nut - Repair - Vehicles Without Occasional Rear Seats Engage /disengage transit mode	86.15.25 86.90.89.30	0.2 0.3	- -	- -
Q663	G	Battery Negative Terminal Nut - Repair - Vehicles Without Occasional Rear Seats Engage /disengage	86.15.25 86.90.89.30 02.02.02	0.2 0.3 0.2	- - -	- - -

		transit mode Drive in/drive out				
--	--	---------------------------------------	--	--	--	--

Normal Warranty policies and procedures apply.

SERVICE
INSTRUCTION:

1

Open the tailgate.


2



E202903


Remove any transit bags from the loadspace.

3



Lift the loadspace board, hook it onto the tailgate opening, and access the spare wheel.

4




Remove the spare wheel fixing and retainer.

5




WARNING:

This step should be completed with the assistance of another technician.




Remove the spare wheel.

6



Fold the carpet back to access the battery.

7



Tighten the nut on the cable connection to the negative terminal bracket.

Torque: **12 Nm** .

8

To install, reverse the removal procedure.