

LTB01048NAS1

TECHNICAL BULLETIN

17 MAY 2017



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

SECTION:

419-10: Multifunction Electronic Modules

SUBJECT/CONCERN:

Door Mirror Glass Does Not Return After Reverse Dip Operation

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
Discovery Sport (LC)	2015-2017	501001-661558	Halewood
Range Rover Evoque (LV)	2016-2017	097712-198146	Halewood

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:

SITUATION:

The left and right door mirror glass may not return to its previously set position following a reverse dip operation.

CAUSE:

This may be caused by a driver and passenger door module software issue.

ACTION:

Should a Customer express this concern, follow the Diagnostic Procedure below.

PARTS:

No Parts Required

TOOLS:



Jaguar Land Rover-
approved Midtronics
battery power supply



Jaguar Land Rover-approved diagnostic tool with latest SDD software, Calibration File

WARRANTY:

NOTES:

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.

- DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Driver and passenger door module - Configure - Discovery Sport (L550)	86.90.89.80	0.2	04	LR092136 / LR078333
Driver and passenger door module - Configure - Range Rover Evoque (L538)	86.90.89.80	0.2	04	LR095503 / LR095501

NOTE:

Normal Warranty procedures apply.

DIAGNOSTIC PROCEDURE:

CAUTIONS:

- **A Jaguar Land Rover-approved Midtronics battery power supply must be connected to the vehicle battery during diagnosis / module programming.**
- **All ignition ON/OFF requests MUST be carried out; failure to perform these steps may cause damage to vehicle control modules.**

NOTE:

The Jaguar Land Rover-approved diagnostic tool must be loaded with DVD149.04 and Calibration File 268 (or later).

- 1 Connect the Jaguar Land Rover-approved Midtronics battery power supply to the vehicle battery.
- 2 Switch the ignition ON (engine not running).
- 3 Connect the Jaguar Land Rover-approved diagnostic tool to the vehicle and begin a new session.
- 4 Follow the on-screen prompts, allowing the diagnostic tool to read the VIN, identify the vehicle, and initiating the data collect sequence.
- 5 Select **Diagnosis** from the Session Type screen.
- 6 Select the **Selected Symptoms** tab and then select:
 - **Body - Rear view mirrors - Exterior rear view mirrors - Reverse mirror dip**
- 7 Select **continue**.
- 8 Select the **Recommendations** tab.
- 9 Select **Run** to perform the '**Configure existing module - Combined door module software**' option.
- 10 Follow all on-screen instructions to complete this task, ensuring all Diagnostic Trouble Codes (DTC) are cleared.

11 When all tasks are complete, select the **Session** tab and then select the **Close Session** option.

12 Disconnect the diagnostic tool and battery power supply from the vehicle.