

Service Bulletin

INFORMATION

Subject: Auto Stop System Does Not Operate During Cold Ambient Temperatures

Brand:	Model:		Mode	l Year:	VIN:		Engine:	Transmission:	
		fro	om	to	from	to			
Chevrolet	Cruze (VIN B)	2016		2017					
Involved Region or Country			North America						
Additional Optic	ons (RPOs)		Equipped with (RPO KL9) ENG CONTROL-STOP/START SYS, CONVENTIONAL AT, CONVENTIONAL MT OR BRAKE RELEASE LATE RESTART						
Condition			Some customers may comment that their auto stop system does not operate during cold ambient temperatures.						
Cause			This condition may be due to the auto stop function does not operate when ambient temperatures are less than 4°C (40°F).						
Correction			This is a normal characteristic and no parts should be replaced for this condition.						

Customer Information

Please communicate to the customer this condition is a normal operating characteristic of their vehicle. It will not impact the designed performance or reliability of the vehicle. Please share this information with the customer, including a copy of this message.

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION