

LTB00610NAS3

TECHNICAL BULLETIN

09 JUN 2017



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

This reissue replaces all previous versions. Please destroy all previous versions.

Changes are highlighted in blue

SECTION:

501-17: Roof Opening Panel

SUBJECT/CONCERN:

Wind Noise at High Vehicle Speeds

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:	APPLICABILITY:
Range Rover Sport (LW)	2014	001154-001204	Solihull	Vehicles With: Roof Opening Panel
Range Rover Sport (LW)	2014-2015	300003-399999	Solihull	Vehicles With: Roof Opening Panel
Range Rover Sport (LW)	2014-2016	500023-599999	Solihull	Vehicles With: Roof Opening Panel
Range Rover Sport (LW)	2014 Onwards	600000 Onwards	Solihull	Vehicles With: Roof Opening Panel
Range Rover Sport (LW)	2016 Onwards	100000 Onwards	Solihull	Vehicles With: Roof Opening Panel
Range Rover (LG)	2013 Onwards	001204 Onwards	Solihull	Vehicles With: Roof Opening Panel

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:

SITUATION:

A wind noise at high vehicle speeds (110mph/176Km/h or above) may be evident from the roof opening panel area.

CAUSE:

This may be due to ram air causing the roof opening panel weatherstrip to vibrate against the vehicle roof.

ACTION:

Should a customer express this concern, follow the Service Instruction outlined below.

PARTS:

PART NUMBER	DESCRIPTION	QUANTITY:
LR040765	Kit Glass Adhesive	1

WARRANTY:**NOTES:**

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.
- The JLR Claims Submission System requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero


DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Seal the roof opening panel weatherstrip	05.10.10	0.1	42	LR048607

NOTE:

Normal Warranty procedures apply.

COMPONENT LOCATION:

1




Area of the vehicle to be worked on.

SERVICE INSTRUCTION:

1

NOTE:

Make sure the area is clean and dirt free.



Use a suitable cloth to clean the area to be worked on.


-
- 2 Cut the nozzle of the sealer to a maximum of 2mm.
-

3 **CAUTION:**

Make sure no damage is caused to the vehicle.

NOTE:


Locate the center line of the vehicle.



Starting from the center of the vehicle, use a suitable trim tool to raise the edge of the seal.

4 **CAUTION:**

Make sure no damage is caused to the vehicle.




Insert the nozzle of the sealer gun.

- Remove the suitable trim tool.

5

NOTE:

Do not use an excessive amount of sealer.



Insert the sealer using the sealer gun.


- Slowly move the sealer gun towards you, allowing a even amount of sealer to be placed between the seal and vehicle body.

6 Repeat steps 5-6 for the other side of the sunroof seal.

7

NOTE:

Allow the sealer to dry for a minimum 45 minutes before washing the vehicle.



Use a suitable cloth to clean any excess sealer.