

N053 UPS4217-1BNAS1

# TECHNICAL BULLETIN

01 JUN 2017



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

---

SECTION:

413-08: Information and Message Center

---

SUBJECT/CONCERN:

Update Prior to Sale: Autonomous Emergency Braking (AEB), Driver Fatigue and Driver Assistance Features Unavailable In the Instrument Cluster Menu

---

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
Discovery (LR)	2017	001728-011873	Solihull

---

MARKETS:

NORTH AMERICA

---

CONDITION SUMMARY:

SITUATION:

An issue has been identified on certain vehicles within the listed Affected Vehicle Range where, as a result of a prior Car Configuration File (CCF) update, the Autonomous Emergency Braking (AEB) and Driver Fatigue Alert features are not available for selection in the Instrument Cluster Driver Assistance menu.

**NOTE:**

**If eligible, perform Service Action N027 BEFORE performing N053.**

ACTION:

Retailers are required to **HOLD** affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the Diagnostic Procedure detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but **must** have it completed prior to vehicle handover to the customer.

---

PARTS:

No parts required.

---

## SPECIAL TOOLS:



E192494

Jaguar Land Rover-approved Midtronics Battery Power Supply



E179225

Jaguar Land Rover-approved diagnostic tool with latest PATHFINDER software

---

## WARRANTY:

**NOTE:**

---

**Check DDW to ensure that a vehicle is affected by this program (N053) and N027 prior to undertaking any rework action. If eligible, perform Service Action N027 BEFORE performing N053.**

At the time of confirming a booking for vehicle repair, ensure that **all** outstanding Recall and Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting the Program Code together with the relevant Option Code. The SRO and parts information is included for information only. The Option Code(s) that allows for the drive in/drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **16 May 2018** closure date must be submitted or payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS/SUNDRY CODE	QTY./VALUE
N053	B	Image Processing Control Module - Learn procedure	05.10.20	0.20	-	-
N053	C	Image Processing Control Module - Learn procedure Drive in/drive out	05.10.20 02.02.02	0.20 0.20	- -	- -

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS/SUNDRY CODE	QTY./VALUE
N053	D	Image	05.10.20	0.20	-	-
		Processing	88.90.60	0.10	-	-
		Control Module - Learn procedure				
		Pathfinder - Transit Mode - Engage				
N053	E	Image	05.10.20	0.20	-	-
		Processing	88.90.60	0.10	-	-
		Control	02.02.02	0.20	-	-
		Control Module - Learn procedure				
		Pathfinder - Transit Mode - Engage				
		Drive in/drive out				

Normal Warranty policies and procedures apply.

DIAGNOSTIC PROCEDURE:

---

**CAUTIONS:**

- **A Jaguar Land Rover-approved Midtronics battery power supply must be connected to the vehicle battery during diagnosis / module programming.**
- **Make sure all ignition ON/OFF requests are carried out; failure to perform these steps may cause damage to control modules in the vehicle.**

**NOTES:**

- **The Jaguar Land Rover-approved diagnostic tool must be loaded with PATHFINDER version 84 (or later).**

- **If eligible, perform Service Action N027 BEFORE performing N053.**

---

1 Connect the Jaguar Land Rover-approved Midtronics battery power supply to the vehicle battery.

---

2 Connect the Jaguar Land Rover-approved diagnostic tool to the vehicle and begin a new session.

---

3 **NOTE:**

**The Jaguar Land Rover-approved diagnostic tool will read the correct Vehicle Identification Number (VIN) for the current vehicle and automatically take the vehicle out of Transit mode if required.**

Follow the on-screen prompts.

---

4 Select **ECU Diagnostics**.

---

5 Select **Image Processing Module 'A' [IPMA]**.

---

6 Select **ECU functions**.

---

7 Select **Allow Central Configuration Data Learning**.

---

8 Follow all on-screen instructions to complete this task.

1 If required, reset the vehicle to **Transit mode**.

---

9 When all tasks are complete, exit the current session.

---

10 Disconnect the diagnostic tool and battery power supply from the vehicle.

