



UPDATE PRIOR TO SALE N053: AUTONOMOUS EMERGENCY BRAKING (AEB), DRIVER FATIGUE AND DRIVER ASSISTANCE FEATURES UNAVAILABLE IN THE INSTRUMENT CLUSTER MENU

SERVICE BULLETIN

01-JUN-17

NO.: SGI17-26

SEC.: GENERAL INFORMATION

MKT.: CAN / USA

DESCRIPTION OF ISSUE

A potential issue has been identified on a limited number of Land Rover vehicles within the listed Affected Vehicle Range where, as a result of a prior Car Configuration File (CCF) update, the Autonomous Emergency Braking (AEB) and Driver Fatigue Alert features are not available for selection in the Instrument Cluster Driver Assistance menu.

AFFECTED VEHICLE RANGE

Discovery (L462)

Model Year: 2017

VIN: 001728-011873

Visit the InfoTrail website for a list of affected unsold vehicles (as of 31 May 2017).

ACTION TO BE TAKEN

Check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action.

Retailers are required to HOLD affected new vehicles that are within your control and refrain from releasing the vehicles for new vehicle sale pending completion of the rework action.

Refer to Technical Bulletin N053 UPS4217-1bNAS, *Update Prior to Sale: Autonomous Emergency Braking (AEB), Driver Fatigue and Driver Assistance Features Unavailable In the Instrument Cluster Menu*, for detailed repair instructions.

PARTS

No parts required.

TOOLS

Refer to Technical Bulletin noted above for any required tools.

WARRANTY

NOTE: check DDW to ensure that a vehicle is affected by this program (N053) and N027 prior to undertaking any rework action. If eligible, perform Service Action N027 BEFORE performing N053.

At the time of confirming a booking for vehicle repair, ensure that **all** outstanding Recalls and Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting the Program Code together with the relevant Option Code. The SRO and parts information is included for information only. The Option Code(s) that allows for the drive in/drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **16 May 2018** closure date must be submitted for payment within 30 calendar days of completion of the repair.

| PROGRAM CODE | OPTION CODE | DESCRIPTION | SRO | TIME (HOURS) | PARTS / SUNDRY CODE | QTY. / VALUE |
|--------------|-------------|---------------------------------------------------|----------|--------------|---------------------|--------------|
| N053 | B | Image Processing Control Module - Learn procedure | 05.10.20 | 0.20 | - | - |
| N053 | C | Image Processing Control Module - Learn procedure | 05.10.20 | 0.20 | - | - |
| | | Drive in/drive out | 02.02.02 | 0.20 | - | - |
| N053 | D | Image Processing Control Module - Learn procedure | 05.10.20 | 0.20 | - | - |
| | | Pathfinder - Transit Mode - Engage | 86.90.60 | 0.10 | - | - |
| N053 | E | Image Processing Control Module - Learn procedure | 05.10.20 | 0.20 | - | - |
| | | Pathfinder - Transit Mode - Engage | 86.90.60 | 0.10 | - | - |
| | | Drive in/drive out | 02.02.02 | 0.20 | - | - |

Normal Warranty policies and procedures apply.

CUSTOMER COMMUNICATION

Should this Program mean that you are unable to deliver an affected vehicle to a customer at an agreed handover date, please advise the customer of the following:

'Jaguar Land Rover is committed to delivering vehicles to our customers of the highest quality, complete with the very latest hardware and software. Our vehicles are continually evolving, with our Engineering and Design teams constantly looking for new and innovative ways to further enhance and develop our vehicles.

Jaguar Land Rover has advised us that there is an upgrade to be carried out on your vehicle, and have instructed us to complete this action prior to handing the vehicle over to you. Jaguar Land Rover apologize that this upgrade may delay the delivery of your new vehicle but are committed to ensuring customers benefit from the very latest technology to ensure your ownership experience is the best one possible.'

If necessary, you may communicate technical details of the repair or upgrade that is required on the vehicle; this is at your discretion.

RETAILER EMPOWERMENT

We appreciate the frustration experienced by both our customers and Retailers with regards the launch of any Update Prior to Sale program.

Following the launch of Retailer Empowerment (and where you feel it appropriate), you now have the ability to offer goodwill to customers who have suffered delays in the delivery of their vehicle. Any goodwill offer should be specifically for a customer whose vehicle delivery has been delayed due to this specific activity to acknowledge the poor experience.

Should you have any questions, please contact the Customer Relationship Centre (CRC) in the first instance for help and support.