

LTB01026NAS1

TECHNICAL BULLETIN

09 JAN 2017



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

SECTION:

309-00A

SUBJECT/CONCERN:

Rattle Noise Under Vehicle / Exhaust System Rear Heat Shield Cracked

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
Range Rover Evoque (LV)	2012 Onwards	600000 Onwards	Halewood

MARKETS:

NAS

CONDITION SUMMARY:**SITUATION:**

A rattle noise from underneath the rear of the vehicle may be evident. Upon further inspection the exhaust system rear heat shield is found to be cracked.

CAUSE:

This may be caused by components which are manufactured outside of specification.

ACTION:

Should a Customer express this concern, follow the Service Instruction below.

PARTS:

PART NUMBER	DESCRIPTION	QUANTITY:
LR026557	Rear exhaust heat shield	1
LR003643	Nut stamped M5 HF	6

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:

NOTES:

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.
- DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Heat shield - Rear - Renew - GTDi 2.0L Petrol	30.10.44	0.6	01	LR026557

NOTE:

Normal Warranty procedures apply.

SERVICE INSTRUCTION:


1

WARNING:

Make sure to support the vehicle with axle stands.

Raise and support the vehicle (see TOPIx Workshop Manual section 100-01: General Information - Jacking and Lifting).

2




Remove the exhaust system rear mountings.

3

WARNING:

This step requires the aid of another technician.




Remove the exhaust system rear section.

4

NOTE:

Both the heat shield and fasteners should be discarded.




Remove and discard the exhaust system rear heat shield and fasteners.

5

NOTES:

- Both a new exhaust system rear heat shield and all fasteners should be used.
- All six replacement exhaust system rear heat shield fasteners will be of the same style.





Install the new exhaust system rear heat shield and fasteners.

- Torque: **2.5 Nm**.

6

WARNING:

This step requires the aid of another technician.




E133353

Install the exhaust system rear section.

- Torque: **55 Nm.**

7 



E133352

Install the rear exhaust system rear mountings.

-
- 8 Lower the vehicle.