

LTB01002NAS1

# TECHNICAL BULLETIN

03 FEB 2017



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

---

---

SECTION:

501-08

---

SUBJECT/CONCERN:

## A-Pillar Moulding Rubber Seal Adrift

---

AFFECTED VEHICLE RANGE:

| MODEL:                  | MODEL YEAR: | VIN:          | ASSEMBLY PLANT: |
|-------------------------|-------------|---------------|-----------------|
| Range Rover Evoque (LV) | 2012-2017   | 600001-203731 | Halewood        |

---

MARKETS:

NAS

---

CONDITION SUMMARY:

## SITUATION:

The A-Pillar moulding rubber may be adrift or a wind noise from the front windshield area may be evident.

## CAUSE:

This may be caused by the manufacturing process deviating from standard, causing the adhering process to not be as efficient as required.

## ACTION:

Should a Customer express this concern, follow the Service Instruction below.

---

PARTS:

| PART NUMBER | DESCRIPTION                   | QUANTITY: |
|-------------|-------------------------------|-----------|
| LR077218    | A-Pillar Moulding LH Black    | 1         |
| LR077217    | A-Pillar Moulding RH Black    | 1         |
| LR002162    | 4.8 x 20mm Cross Recess Drive | 4         |
| RYH500840   | M4 Plastic Nut                | 4         |
| LR033144    | HC1 Clip                      | 10        |

| PART NUMBER | DESCRIPTION | QUANTITY: |
|-------------|-------------|-----------|
| LR002229    | Grommet     | 10        |

## TOOLS:

Refer to Workshop Manual for any required special tools.

## WARRANTY:

### NOTE:

DDW/WASP requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

### NOTES:

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.
- DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

| DESCRIPTION                                   | SRO      | TIME<br>(HOURS) | CONDITION<br>CODE | CAUSAL<br>PART |
|---|----------|-----------------|-------------------|----------------|
| Moulding - Windshield - Left side -<br>Renew  | 76.43.39 | 0.1             | D8                | LR077217       |
| Moulding - Windshield - Right side<br>- Renew | 76.43.40 | 0.1             | D8                | LR077217       |

### NOTE:

Normal Warranty procedures apply.

## SERVICE INSTRUCTION:

- 1 Remove and discard the affected A-Pillar moulding (see TOPIx Workshop Manual section 501-08: Exterior Trim and Ornamentation - A-Pillar Moulding).

2



Visually inspect the date printed on the label attached to the new A-Pillar moulding.

- If the printed date is **25/11/16** or later, the part can be installed. Go to step 3.
- If the printed date is **24/11/16** or earlier, the part must not be installed.
  - Source a new A-Pillar moulding with a printed date of 25/11/16 or later.
  - Go to Step 3.

- 3 Install the new A-Pillar moulding (see TOPIx Workshop Manual section 501-08: Exterior Trim and Ornamentation - A-Pillar Moulding).

- Repeat steps 1-3 for the other moulding if required.