

JTB00549NAS1

**TECHNICAL BULLETIN**

29 MAR 2017



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

**INFORMATION**

---

**SECTION:**

---

413-13

---

**SUBJECT/CONCERN:**

---

Parking Aid System Sounds With No Objects Nearby

---

**AFFECTED VEHICLE RANGE:**

<b>MODEL:</b>	<b>MODEL YEAR:</b>	<b>VIN:</b>	<b>ASSEMBLY PLANT:</b>
F-PACE (X761)	2017 Onwards	045068 Onwards	Solihull

---

**MARKETS:**

NORTH AMERICA

---

**CONDITION SUMMARY:****SITUATION:**

The front Parking Aid System may sound when no objects are nearby the vehicle.

**CAUSE:**

This may be caused by the front bumper interfering with the parking aid sensor reporting area.

**ACTION:**

Should a Customer express this concern, follow the Diagnostic Procedure below.

---

**PARTS:**

No Parts Required

---

**TOOLS:**



Jaguar Land Rover-approved Midtronics battery power supply



Jaguar Land Rover-approved diagnostic tool with latest SDD software, Calibration File, and InControl© Touch Pro™ Software

**WARRANTY:****NOTES:**

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPlx to obtain the latest repair time.
- DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Configure Parking Assist Control Module (PAM)	86.98.17	0.1	42	C2D50699

**NOTE:**

Normal Warranty procedures apply.

**DIAGNOSTIC PROCEDURE:****CAUTIONS:**

- **A Jaguar Land Rover-approved Midtronics battery power supply must be connected to the vehicle battery during diagnosis / module programming.**
- **Make sure all ignition ON/OFF requests are carried out; failure to perform these steps may cause damage to control modules in the vehicle.**

**NOTE:**

**The Jaguar Land Rover-approved diagnostic tool must be loaded with DVD149.00 and Calibration File 264 (or later).**

- 1 Connect the Jaguar Land Rover-approved Midtronics battery power supply to the vehicle battery.
- 2 Switch the ignition ON (engine not running).
- 3 Connect the Jaguar Land Rover-approved diagnostic tool to the vehicle and begin a new session.
- 4 Follow the on-screen prompts, allowing the diagnostic tool to read the VIN, identify the vehicle, and initiating the data collect sequence.
- 5 Select **Diagnosis** from the Session Type screen.
- 6 Select the **Selected Symptoms** tab and then select:
  - **Electrical - Driving aids - Parking aid**
- 7 Select **continue**.
- 8 Select the **Recommendations** tab.
- 9 Select **Run** to perform the '**Configure existing module - Parking assist control module**' option.
- 10 Follow all on-screen instructions to complete this task, ensuring all Diagnostic Trouble Codes (DTC) are cleared.
- 11 When all tasks are complete, select the **Session** tab and then select the **Close Session** option.
- 12 Disconnect the diagnostic tool and battery power supply from the vehicle.

