

40 Creaking/squeaking noises from front end on uneven roads

40 17 59 2043424/3 February 27, 2017. Supersedes Technical Service Bulletin Group 40 number 16-53 dated June 2, 2016 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
А3	2015 - 2017	All	Not Applicable

Condition

REVISION HISTORY						
Revision Date Purpose						
3	-	Revised <i>Technical Background</i> (Added picture and note) Revised <i>Service</i> (Updated instructions and added picture) Revised header data (Added model years and removed VIN break)				
2	06/02/2016	Revised header data (Added customer codes)				
1	02/22/2016	Initial publication				

Creaking/squeaking noises are heard from the left front or right front area of the vehicle when it is driven on uneven roads.

Technical Background



Try to duplicate this condition exactly. If you cannot, do not perform this TSB.



Overview of the lower control arm and bushing (Figure 1).




Figure 1. Lower control arm and bushing.



The rear bonded rubber bushings of the front lower control arms have a kidney-shaped slits (Figure 2). When the vehicle is driven on uneven roads, areas A and B (Figure 2) may come in contact, creating the creaking/squeaking noise.




Figure 2. Kidney-shaped slits (yellow arrows) of the rear bonded rubber bushings.

Production Solution

Not applicable.



Service

- 1. Remove both front lower control arms. Follow instructions in ElsaPro for *Repair Manual* >> Chassis >> Suspension, Wheels, Steering >> Front Suspension >> Lower Control Arm and Ball Joint >> Lower Control Arm, Removing and Installing.
- Evenly grease the kidney-shaped slits of the bonded rubber bushing (Figure 3, the area shown red) from above with 0.1g of lithium grease (part number G 052 150 A2). Use a paint brush to apply the grease.



Note that the lithium grease must only be applied to the areas shown in red (Figure 3).



Figure 3. Lithium grease is applied on the red highlighted area only.

3. Reinstall all components according to Elsa.



Warranty

	T					
Claim Type:	• 110 up to 48 Months/50,000 Miles.					
	G10 for CPO Covered Vehicles – Verify Owner.					
	If vehicle is outside any warranty, this Technical Service Bulletin is informational only.					
Service Number:	4020					
Damage Code:	0020					
Labor Operations:	Both lower control arms remove + reinstall	4017 2001	250 TU			
	Grease the bonded rubber bushings	4020 4199	10 TU			
Diagnostic Time:	GFF	No allowance	0 TU			
	Road test prior to service procedure	0121 0002	10 TU			
	Road test after service procedure	0121 0004	10 TU			
	Technical diagnosis at dealer's discretion					
	(Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)					
Claim Comment:	As per TSB #2043424/3					

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
G 052150A2	Lithium grease	0.1
See ETKA	One-time use hardware according to Elsa	As needed



Additional Information

All parts and service references provided in this TSB (2043424) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.