



# Technical Service Bulletin

---

## 45 ABS light illuminated (DTC 01130 and/or DTC 16352)

45 17 11 2046907/1 February 17, 2017.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3	2009	All	Not Applicable

## Condition

- ABS light is illuminated.
- Safety Recall 45F5 shows closed in Elsa.

One or both of the following DTCs is stored in the ABS control module, J104 (address word 0003):

- **DTC 01130** (ABS operation – implausible signal), with 125 shown in the 4<sup>th</sup> line of the expanded ambient conditions.
- **DTC 16352** (control module faulty), with 96 shown in the 4<sup>th</sup> line of the expanded ambient conditions.

## Technical Background

An insufficient PCU ground connection in the ABS control module could cause the module to fail during ABS and/or electronic stability control (ESC) activation. Safety Recall 45F5 updated the ABS control module software with improved diagnostic capability to detect these faults.

## Production Solution

Not applicable.

## Service

1. Ensure that Safety Recall 45F5 shows closed in Elsa before proceeding.
2. Replace the ABS control module.

## Warranty



# Technical Service Bulletin

<b>Claim Type:</b>	<ul style="list-style-type: none"> <li>• 110 – Verify Vehicle Warranty Coverage.</li> <li>• If vehicle is outside any warranty, this Technical Service Bulletin is informational only.</li> </ul>		
<b>Service Number:</b>	4545		
<b>Damage Code:</b>	0040		
<b>Labor Operations:</b>	Hydraulic unit remove + reinstall	4530 1950	130 TU
	ABS/EDL control module replace	4545 5550	130 TU
	Brake system bleed (pre-bleed)	4701 0760	30 TU
	Brake system bleed (post-bleed)	4701 0770	30 TU
	Wheels remove + reinstall	4405 2000	20 TU
<b>Diagnostic Time:</b>	GFF	0150 0000	30 TU
	Road test prior to service procedure	0121 0002	10 TU
	Road test after service procedure	0121 0004	10 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
<b>Claim Comment:</b>	As per TSB #2046907/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Required Parts and Tools

Part Number	Part Description	Quantity
See ETKA	ABS control module	1

## Additional Information



# Technical Service Bulletin

---

All parts and service references provided in this TSB (2046907) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.