



Technical Service Bulletin

91 Apple CarPlay black screen immediately after using backup camera or distorted audio during Bluetooth call

91 17 09 2046294/1 February 24, 2017.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4	2017	All	MIB2 High Scale

Condition

The customer has one or both of the following conditions:

- When trying to use Apple CarPlay the screen is blank only after using the backup camera. This issue occurs immediately after exiting the camera image by driving forward or by manually pressing the parking aid button to deactivate the backup camera image
- When using Bluetooth hands-free calling the caller hears distorted audio from the driver that can be described as a "robotic or electronic sound".

Additionally the following must be true:

- The vehicle is equipped with MMI Radio plus (PR code 7UH)



Note:

The vehicle was built before CW22 of 2016. All cars built after should not be updated because possible damage can occur.

Technical Background

These are known software concerns which only exists with 2017 A4 vehicles which were built with the base MMI system that does not have navigation nor an internal jukebox hard drive. This MMI system is called MIB2 High Scale (or MMI Radio Plus). The concern was resolved in vehicles built after CW22/16 with production SW0110 or service SW0118 or higher.

How to reproduce the CarPlay concern:

1. Let the vehicle bus go to sleep (MMI must be completely asleep and not initialized).
2. Disconnect ODIS, roll up windows, and lock car for 3-5 minutes.
3. Once asleep, unlock and start the vehicle.
4. Connect an iPhone to the MMI using USB slot 1.

Technical Service Bulletin

5. Allow CarPlay to load and show in the MMI display.
6. Shift the car into reverse or push the parking aid button to activate the rear camera.
7. Shift the car into drive and drive off or manually turn off the parking aid using the button.
8. At this point the MMI screen will go black if the customer's car is affected. The audio playing from CarPlay will continue, but the MMI screen will go black.
9. To fix the concern disconnect and reconnect the iPhone from the USB.

How to reproduce the Bluetooth hands-free call concern:

1. Pair a phone to the MMI.
2. Allow the phone book to sync to the MMI.
3. Initiate a call using the MMI.
4. Ask the caller if your voice sounds distorted or electronic.

Production Solution

Software improvement introduced into series production.

Service

The service solution is to update the MMI software to SW0118 to fix the Bluetooth call and CarPlay blank screen concern when coming out of reverse only for MMI Radio plus.



Note:

If the MMI software is SW0061 then this update can possibly remove the Speech Dialog System (VR) feature. Please test the Voice Recognition/Speech Dialog System after performing the update. If the VR/SDS feature is no longer available, a message of "Please wait" is seen after pressing the button on the steering wheel, then contact the Audi Technician's helpline.

Required equipment:

- ODIS Tester
- MIB2 High Scale Software Update on SD Card (See required parts & tools information table below)
- SVM code MI2HSNAR130 (also listed in steps below)

Time to complete update:

Technical Service Bulletin

- Approximately 90 minutes (includes S/W update and SVM work)

Repair procedure:

1. Verify the customer's MMI requires the software update by going to the *Main Menu>>Settings>>Left drawer option>>Version Information* (Figure 1).



Note:

Software versions 0061 & 0081 are only the versions which can be updated. If the MMI is at a level greater than 0110 (e.g. 0112, or 0118), then this TSB does not apply.



Figure 1. MMI Version Information

2. Obtain the SD card from the parts department (see parts and tools table below).
3. Connect a charger or battery maintainer to the vehicle that capable of maintaining the vehicle voltage at the appropriate levels (check current capacity of maintainer). Turn off all unnecessary battery consumers, such as LED DRL's, HVAC blower, radio volume mute, etc.).
4. Follow the steps listed in the attached document "MIB2_High_Scale_Software_Update.pdf" to complete the update process. Enter the Red Engineering Update menu using the procedure listed in the instructions. Do not use the White Customer Update menu found under *Menu >> Settings*. Performing the update in the White Customer Update menu will only update the Bluetooth firmware and nothing else. Please perform the full update in the Red Engineering Update menu.
5. Perform the SVM feedback documentation of the information control unit 1 J794 (diagnosis address 005F – MMI) with SVM using the SVM code **M12HSNAR130**. To access SVM, within ODIS start *GFF >> Diagnosis >> Special functions >> Software Version Management >> SVM code input*.

Test the functionality of CarPlay and Bluetooth hands-free call after the update using the steps listed in the Technical Background. It is important to remember to allow the car to go to sleep before performing the test. Test the functionality of Voice Recognition after the update is completed. If the concern is not resolved or if VR becomes disabled then please contact Audi Technician's helpline (TAC).



Technical Service Bulletin

Warranty

Claim Type:	<ul style="list-style-type: none">• 110 up to 48 months/50,000 miles.• G10 for CPO Covered Vehicles - Verify Owner.• If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9196		
Damage Code:	0039		
Labor Operations:	Program infotainment control unit & Test Functionality	9196 9999	175 TU
Diagnostic Time:	GFF	0150 0000	Time stated on diagnostic protocol (Max 100 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
Claim Comment:	As per TSB #2046294/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
4M0.906.961.AG	MIB2 High Scale Software Update SD card	1 per dealer (shop tool)



Technical Service Bulletin

Additional Information

All parts and service references provided in this TSB (2046294) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.