

# Technical Service Bulletin



## 20Y4 UPDATE – ECM Software Update (FED\_EMS)

February 10, 2017

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4 allroad, A4, A5 Cabriolet, A5 Coupe, Audi Q5	2015-2016	See Campaign/Action screen in Elsa	None

REVISION HISTORY		
Revision	Date	Purpose
1	February 09, 2017	Original publication
2	February 10, 2017	Saga claiming instructions updated.

## Condition

This Update has been proactively released to prevent the following condition from occurring in the vehicle:

Update ECM software to improve diagnostic of NVLD system.

This Update is in effect until removed.

Vehicle must meet all of the following criteria:

- Procedure is valid only for vehicles that show the **20Y4** code in the Elsa Campaign/Action Information screen on the day of repair.
- Vehicle must be within the Federal Emissions Warranty.
- Procedure must be performed within the allotted time frame stated in this Technical Service Bulletin.
- Procedure must be performed on applicable vehicles in dealer inventory prior to sale.

## Technical Background

Update ECM software to improve diagnostic of NVLD system.



## Service

### SVM Update Instructions

1. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions.*
2. Attach an appropriate battery charger to the vehicle.
3. Attach the scan tool to the vehicle using an USB cable.
4. Confirm that the scan tool is communicating with the diagnostic head by USB <Green Arrow>. If the Bluetooth symbol is shown <Red Arrow> then disconnect the diagnostic head from the vehicle and then reattach the USB cable to the diagnostic head and then reattach to the vehicle.



5. Using Flashing, perform the update using the SVM action code, **20Y4A200**.
6. After the Flashing test plan has completed upload log online.



## Warranty

### Claim Entry Instructions

After campaign has been completed, enter claim as soon as possible to help prevent work from being duplicated elsewhere. Attach the Elsa screen print showing action *open on the day of repair* to the repair order.

If customer refused campaign work or vehicle is out of the specified warranty parameter for this Update:

- ✓ U.S. dealers: Submit the request through Audi Warranty Online under the Campaigns/Update option.
- ✓ Canada dealers: Fax repair order to Warranty at (905) 428-4811.

<b>Service Number</b>	20Y4	
<b>Damage Code</b>	0099	
<b>Parts Vendor Code</b>	002	
<b>Claim Type</b>	Sold vehicle: 7 10 Unsold vehicle: 7 90	
<b>Causal Indicator</b>	Mark labor as causal part	
<b>Vehicle Wash/Loaner</b>	Do not claim wash/loaner under this action	
<b>Criteria I.D.</b>	4G or 8F or 8K or 8R or 8T	
	Connect battery charger. Labor operation: 2706 8950                      10 T.U.	
	<b>-AND-</b>	
	Update software via SVM. Labor operation: 2470 2599                      Time stated on diagnostic protocol (max 50 T.U.)	

# Technical Service Bulletin

---



- Additional Actions** Some of the affected vehicles may be involved in additional Actions. Please check your Elsa Campaign/Action Information screen so that any *additional required work can be done simultaneously.*
- Verifying Vehicle Eligibility** To verify vehicle eligibility for this Update, *always* check the Elsa Campaign/Action Information screen. The Elsa system is the *only* binding inquiry and verification system; other systems are not valid and *may result in non-payment* of a claim.
- Help for Claim Entry** For questions regarding claim entry, contact Audi Warranty.
- Required Customer Notification** Inform your customer in writing by recording on the Repair Order any and all work that was conducted on the vehicle, including any and all updates completed under this Update.

## Additional Information

All parts and service references provided in this Update are subject to change and/or removal. Always check Elsa for the most current version of this document.