

# Technical Service Bulletin

Mazda North American Operations  
Irvine, CA 92618-2922

**Subject:**

**CHECK ENGINE LIGHT ON WITH DTC P2183:00**

**Bulletin No.:** 01-011/17

**Last Issued:** 08/04/2017

**APPLICABLE MODELS/VINS**

2014-2017 Mazda3 with VINS starting with 3MZ

2014-2017 Mazda3 with VINS lower than JM1B\*\*\*\*\*153241 (produced before May 16, 2017)

**DESCRIPTION**

If a customer brings their vehicles in with DTC P2183:00 stored, repair the vehicle using the following Repair Procedure and Caution.

- P2183:00: ECT sensor No.2 circuit range/performance problem

This is caused by the ECT sensor No.2 located near the bottom of the radiator getting wet and water entering the part due to insufficient water resistance. To correct this issue, the water resistance of the ECT sensor No.2 has been improved.

**REPAIR PROCEDURE**

1. Verify customer concern.
2. Check ECT sensor PIDs on Data Logger with Mazda Modular Diagnostic System (M-MDS).

- ECT: Engine Coolant Temperature
- ECT2\_V: ECT sensor No.2 voltage

If the ECT sensor No.2 internal circuit is corroded, the sensor output is far below the ECT sensor No.1 output due to higher resistance caused by corrosion.

Determine if the ECT sensor No.2 is malfunctioning by comparing the two sensors outputs.

Output (V)	4.84	4.79	4.72	4.64	4.55	4.43	4.30	4.14	3.96	3.77	3.56
Temp (°C)	-40	-35	-30	-25	-20	-15	-10	-5	0	5	10
Temp (°F)	-40	-31	-22	-13	-4	5	14	23	32	41	50

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Output (V)	3.33	3.10	2.86	2.63	2.39	2.17	1.95	4.14	1.57	1.40	1.25
Temp (°C)	15	20	25	30	35	40	45	50	55	60	65
Temp (°F)	59	68	77	86	95	104	113	122	131	140	149


Output (V)	1.11	0.99	0.87	0.78	0.69	0.61	0.55	0.48	0.43	0.38	0.34
Temp (°C)	70	75	80	85	90	95	100	105	110	115	120
Temp (°F)	158	167	176	185	194	203	212	221	230	239	248

3.If the ECT sensor No.2 is determined to be "NO GOOD", replace it with a modified one according to the Workshop Manual "ENGINE COOLANT TEMPERATURE (ECT) SENSOR REMOVAL/INSTALLATION [SKYACTIV-G 2.0, SKYACTIV-G 2.5]."

**NOTE:** Corroded contact pins can be seen if badly corroded, but no corrosion may be seen if the pins are only corroded in back.

## PARTS INFORMATION

Parts Number	Description	Qty.
PE18-18-840	Sensor, Temp Eng Coolant (A)	1
9956-21-200	Gasket (B) at Radiator (C)	1



**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

## WARRANTY INFORMATION

### NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Federal Emission Warranty or CAPZEV Emission Warranty.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	6X
Damage Code	9W
DTC Code	P2183
Part Number Main Cause	PE18-18-840
Quantity	1
Operation Number / Labor Hours:	XXN67XRX / 0.7 Hrs.

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.