Technical Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



Subject:

KNOCKING / SQUEAKING NOISE FROM FRONT SHOCK ABSORBER, CREAKING NOISE FROM FRONT LOWER ARM BUSHING Bulletin No.: 02-003/17

Last Issued: 08/29/2017

BULLETIN NOTES

This bulletin supersedes the previously issued bulletin(s) listed below: The changes are noted in Red beside the change bars.

Previously issued TSBs:	Date issued:
02-003/17	06/09/2017, 01/13/17 and 03/02/017
02-010/16	10/10/2016, 07/21/2016, 04/05/2016, 03/10/2016
02-006/16	02/23/2016
02-003/15	12/17/2015 and 02/04/2015
02-001/15	11/20/2015 and 01/14/2015
02-005/14	12/12/2014
02-005/13	08/24/2013 and 11/11/2013

APPLICABLE MODEL(S)/VINS

2016 CX-3 vehicles with VINs lower than JM1 DK ****** 136727 (produced before March 07, 2016)

2013-2016 CX-5 vehicles with VINs lower than JM3 KE ****** 896280 (produced before November 7, 2016)

2014-2016 Mazda6

2017 Mazda6 vehicles with VINs lower than JM1 GL ****** 117187 (produced before November 7, 2016)

(NOTE: 2016 CX-9 has been removed from this TSB. For CX-9 refer to bulletin 02-007/17)

Page 1 of 12


Bulletin No.: 02-003/17 **Last Issued:** 08/29/2017

DESCRIPTION

Some vehicles may exhibit a knocking / squeaking noise from the front shock absorber when driving on rough roads and/or when turning the steering wheel while the vehicle is stopped.

The noise may be due to:

- Upper front strut bearing (A) damage. (CX-5 and Mazda6)
- Squeak type noise between the front strut bearing and coil spring. (CX-3, CX-5 and Mazda6)
- The bump stopper (C) may be contacting the strut bearing when the front shock absorber is compressed, causing a popping noise. (Mazda6 only)
- The front lower arm bushing (D) is making a creak type noise in wet road conditions. (CX-5 and Mazda6).



To eliminate the noise, the following mass-production changes have been made:

- 1. The material and production method of the front strut bearing (A) has been changed. (CX-5 and Mazda6)
- 2. A protector has been installed onto the coil spring. (CX-5 and Mazda6)
- 3. The shape of the bump stopper (C) will be modified in the future. (Mazda6 only)
- 4. The shape of the coil spring has been changed. (CX-3 only)
- 5. Friction of the lower arm bushing has been reduced by adding a dry coating. (CX-5 and Mazda6).

Page **2** of **12**


NOTE: The piston rod nut (B) requires replacement.

Customers having this concern should have their vehicle repaired using the following repair procedure.

REPAIR OUTLINE

1. Use Special Service Tool (SST) ChassisEAR / EngineEAR II Combo JSP06608 or Wireless ChassisEAR JSP97202 to confirm noise is coming from the front suspension when driving over bumps and/or turning the steering wheel while the vehicle is stopped:

NOTE: SST JSP06608 and JSP97202 are available for purchase on Mazda E-Store.



2. Was the noise verified?

- Yes Use the table below to determine if the subject vehicle is a Type A, Type B, Type C, Type D, or Type E vehicle.
- No This bulletin does not apply.

Year	Model	Type A	Туре В	Type C	Туре	Type E
					D	
2014-	Mazda6 JM1GJ*****	100001- 121430	121431- 404928	404929- 488592	All	
2016						
2017	Mazda6			100001- 117187		
	JM1GL*****					
2013-	CX-5 JM3KE*****	100001 -	343674 -	615844 -		
2016		343673	615843	896280		
2016	CX-3 JM1DK*****					100001-
						136727

Page 3 of 12

3. Use the table below to identify the appropriate repair.

Repair	Type A	Type B	Type C	Type D	Type E
(Perform On Both Sides)					
1. Inspect the front strut bearing for damage. If	Perform	Do Not	Do Not	Do Not	Do Not
damaged, replace it.		Perform	Perform	Perform	Perform
2. Install the protector onto the coil spring. (Refer	Dorform	Perform	Do Not	Do Not	Perform
to "Protector Installation Procedure")	Periorini Periorini	Perform	Perform	Perioriii	
3. Replace the lower arm bushing.	Perform	Perform	Perform	Perform	Do Not
	Perioriii	Perioriii	Perionii	Perioriii	Perform
4. Replace the bump stopper. (Mazda6 Only)	Perform	Perform	Perform	Perform	Do Not
4. Replace the bump stopper. (Mazdao Omy)		Perioriii	Perioriii	remonn	Perform

NOTE:


- For removal/installation and disassembly/assembly of the front shock absorber, refer to the workshop manual "FRONT SHOCK ABSORBER AND COIL SPRING DISASSEMBLY/ASSEMBLY".
- Before removing the mounting rubber, put the position mark so the mounting rubber can be installed back in the original position.

CAUTION: It is not necessary to adjust the front wheel alignment because the front shock absorber and the mounting rubber are not replaced. However, make sure to install the mounting rubber to the original position.

REPAIR PROCEDURE


Inspect Front Strut Bearing for damage (For Vehicle Type A only)

- 1. Remove the front strut bearing and coil spring according to the MGSS online instructions or the Workshop Manual (section 02-13 FRONT SHOCK ABSORBER AND COIL SPRING DISASSEMBLY/ASSEMBLY).
- 2. Replace the front strut bearing if damaged*.



Install Protector onto Coil Spring (For Vehicle Type A, B and E)

Coil Spring Protector (A) Installation:




- 1. Starting from the top of the coil spring, degrease the spring 1.5 coils downward.
- 2. Cut a thin strip of paper to 138 mm in length (or use a cloth type measuring tape).

NOTE: For CX-3, use 130 mm in length.

Page **5** of **12**


Bulletin No.: 02-003/17

- 3. Place the strip of paper (or cloth measuring tape) along the inner side of the coil spring starting at point (A).
- 4. Mark the spot on the spring where (B) is. (B) is the starting point for the protector installation.



5. Install the protector (A) onto the coil spring aligning the end (slant cut side) with the marking at spot (B).

NOTE: Install the protector so the gap (C) is evenly aligned around the outer edge of the coil spring.




- 6. The inner side of the protector contains adhesive glue. After installing the protector onto the spring, press the inner side to firmly adhere it to the spring.
- 7. Assemble the coil spring to the strut assembly and make sure the protector is seated onto the bearing even when the shock absorber is fully extended.

Page 6 of 12

Replace Bump Stopper (For all Mazda6 vehicles, Type D)

1. Remove the front strut bearing and coil spring according to MGSS online instructions or the Workshop Manual (section 02-13 FRONT SHOCK ABSORBER AND COIL SPRING DISASSEMBLY/ASSEMBLY).

2. Replace the bump stopper (C).




- 3. Reinstall the front strut bearing and coil spring according to MGSS online instructions or the Workshop Manual (section 02-13 FRONT SHOCK ABSORBER AND COIL SPRING DISASSEMBLY/ASSEMBLY).
- 4. Repeat Steps 1 3 on the opposite side front suspension.
- 5. Verify repair.

Page **7** of **12**

Replace Lower Arm Bushing (For Vehicle Type A, B and C)

- 1. Remove the front lower arm (both sides) according to MGSS online instructions or the Workshop Manual (section 02-13FRONT LOWER ARM REMOVAL/INSTALLATION).
- 2. Remove the front lower arm bushing using the SSTs.

Set SSTs [49 G030 797 and 49 B025 004] and the front lower arm on a shop press as shown in the figure and remove the front lower arm bushing.




Page **8** of **12**

3. Install the front lower arm bushing (D) using SSTs.

NOTE:

1. Early front lower arm bushing (D) service part has a projection (A). Install the front lower arm bushing so that the projection (A) shown in the figure is pointing toward the front and out of the vehicle.

2. Current front lower arm bushing (D) service part does not have a projection (A) and can be installed in either direction.




NOTE:

- Before installing the new bushing, wipe the inside of the outer tube and make sure it is clean.
- Apply soap suds to the front lower arm bushing to facilitate installation.
- If soap suds gets in the inner pipe of the front lower arm bushing, always wipe it off using a cloth.


Page **9** of **12**

CAUTION: Make sure that the bushing has been properly inserted by checking that the tab of the bushing is completely expanded as shown in the OK illustration.



4. After the installation, verify that the front lower arm bushing has been installed to the correct position by the procedure shown in the figure.


Specification: Width: 5.6 +/- 0.8mm (0.22 +/- 0.03 in)



Page 10 of 12

5. Install the front lower arm (both sides) according to MGSS online instructions or the Workshop Manual (section 02-13 FRONT LOWER ARM REMOVAL/INSTALLATION).

NOTE: For the joint sections with rubber bushings, raise the vehicle using a lift, and then temporarily tighten the installation bolts. Then raise the vehicle using a wheel alignment lift rack (A) or lower the vehicle to the ground (to load the suspension). Use a torque wrench (B) to tighten the bolts (C) to the specified tightening torque. The Mazda6 is shown below as an example.



- 6. Inspect the wheel alignment and adjust if necessary.
- 7. Verify repair.

PARTS INFORMATION

Part Number	Description	Qty.	Notes
KR27-34-38X	Front Strut Bearing	1 or 2	Type A only
9YB0-41-237	Piston Rod Nut	2	All
9160-41-237			Non-reuseable nut R
KDY5-34-081	Protector	2	Type A , B and E
GHY9-34-111			Mazda6 only
or	Bump Stopper	2	GHY9-34-111 is a service part
GRT7-34-111			GRT7-34-111 is a mass production part
TK48-34-470	F. Lower Arm Rubber Bushing	2	Type A, B and C

Page **11** of **12**

Bulletin No.: 02-003/17 **Last Issued:** 08/29/2017

WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.
- Type A, B and C repairs have two different causal parts (front shock absorber and lower arm). Submit two (2) separate claims.

Front Shock Absorber			
Repair (All Types)			
	CX-5, Mazda6	CX-5, Mazda6	CX-3
Warranty Type	Α	Α	А
Symptom Code	82	82	82
Damage Code	9A	9A	97
Part Number Main Cause	KR27-34-38X	KR27-34-38X	7777-SP-K08
Quantity	0, 1 or 2	0, 1 or 2	0
Operation Number / Labor	With front lower arm bushing	Without front lower arm	XXL9PBRX / 0.9
Hours	replacement	bushing replacement	Hrs.
	XXK8NDRX / 0.6 Hrs.	XXKBKXRX / 0.9 Hrs.	

Front Lower Arm Repair			
(Type A, B and C)			
	CX-5 and Mazda6		
Warranty Type	A		
Symptom Code	82		
Damage Code	93		
Part Number Main Cause	TK48-34-470		
Quantity	2		
Sublet Code	If Wheel Alignment Check and Adjust was performed outside of shop, claim the		
	actual invoice amount with the sublet code "Z9" for CX-5 and Mazda6.		
Operation Number /	Replace both lower arm bushings		
Labor Hours	Select one applicable repair below		
	1. Wheel Alignment Check Adjust was performed outside of shop. XXK8NARX,		
	0.8Hrs. (CX-5 and Mazda6)		
	2. Wheel Alignment Check Adjust was performed at dealer using 4-wheel		
	alignment tester XXK8NBRX, 1.8Hrs. (CX-5 and Mazda6)		
	3. Wheel Alignment Check Adjust was performed at dealer using 4-wheel		
	alignment tester with Wireless Type.XXK8NCRX, 1.4Hrs. (CX-5 and Mazda6)		

Page 12 of 12