

# **Technical Service Bulletin**

GROUP NUMBER

HYBRID
CONTROL

DATE MODEL

SEPTEMBER, 2017 SONATA HYBRID (YF HEV)

SUBJECT: OIL LEAK AT ELECTRIC OIL PUMP


This TSB supersedes 11-AT-019 to update the Parts Information and Service Procedure.

**Description:** Some Sonata Hybrid (YF HEV) vehicles may experience a small oil leak from the electric oil pump (EOP) seals. If so, follow the Service Procedure in this bulletin to inspect and repair the oil seals between the transmission and EOP.


No drivability issues are associated with this condition.

Applicable Vehicles: 2011~15 Sonata Hybrid (YF HEV) 2.4L

A: Location of the EOP (A)



B: Drops of ATF (B) on the bottom of transmission



### **PARTS INFORMATION:**

MODEL	PART NAME	PART NUMBER		LOCATION	
2011~15 Sonata Hybrid (YF HEV)	Oil Seal	45261-3D000		452623B100 452613D000	
	Oil Seal	45262-3B100			
	O-ring	46131-3D000	0	461313D000	
	Bolt	45227-3D000			

**NOTE**: If the new bolt is not available, apply RTV Silicon Gray, P/N 00232-19061 sealant, or equivalent, to the bolt threads and reuse the bolt.

### **WARRANTY INFORMATION:**

MODEL	OP CODE	OPERATION	OP TIME	CAUSAL PART	NATURE CODE	CAUSE CODE
2011~15 Sonata Hybrid (YF HEV)	46120R00	Electric oil pump	Refer to WEBLTS for LTS time	See Parts Information	B25	ZZ2

TSB #: **17-HC-001** Page 2 of 6

#### SERVICE PROCEDURE

1. Open the rear trunk and open the cover to the safety plug.

Put on insulation gloves.

Pull up on the black tab and pull out the safety plug.




Failure to wear protective gear and perform this procedure may result in accidental injury or death.



2. Without depressing the brake pedal, push the Start-Stop button 2 times to power the cluster.

Attach a GDS and select **Data Analysis**, **BMS** menu **Inverter Capacitor Voltage**. Confirm the **Inverter Capacitor Voltage** is less than 30V.

- If less than 30V, the system voltage is safe for the technician. Go to Step 3.
- If more than 30V, wait until the voltage is within specification. Go to Step 3.




3. Squeeze the tab and disconnect the connector above the oil pump.




TSB #: **17-HC-001** Page 3 of 6

4. Use a screwdriver to push the gray tab to the left and remove the connector.






5. Squeeze the tab and remove the connector for the fluid pressure switch.



6. Remove 3 bolts and one nut. Remove the EOP.




TSB #: **17-HC-001** Page 4 of 6


7. Remove the two oil seals.

Clean the bores where the oil seals are located.

Install new oil seals.



8. Install a new O-ring on the EOP.



9. Reinstall the EOP.

Install a new bolt, P/N 45227-3D000, in the location shown by the arrow.

Reinstall two bolts and one nut.

Tighten the bolts and nut to specification.

Torque: 18~22 lb-ft (25~30 Nm)

## **NOTICE**

If the new bolt is not available, apply RTV Silicon Gray, P/N 00232-19061, or equivalent, to the bolt threads.



TSB #: **17-HC-001** Page 5 of 6


- Reconnect the connectors to the EOP and the fluid pressure switch.
   Reconnect the safety plug.
- 11. Remove the transaxle fill plug.

Use a fluid pump to add SP4-M ATF through the fill plug opening. Reinstall the fill plug.

Attach the GDS and select **Data Analysis** and **Oil Temperature Sensor**.

Start the engine and shift to Park. When the ATF is 122°F~140°F (50~60°C), remove the level checking plug. The level is correct when oil flows out of the level checking plug in a thin steady stream.

Collect and dispose of any excess fluid in accordance with local regulations.



12. Depress the brake pedal and press the **SSB** to enable **EV Ready**.

Check for leaks from the oil pump.

Reinstall the splash shield under the transmission.

Attach a GDS and select **Data Analysis, A/T** menu and **Oil Pump Speed Actual RPM**. In "**EV Ready**" mode, confirm the **Oil Pump Speed Actual RPM** is above 400 rpm when the engine is off.

13. Drive the vehicle and confirm the proper operation of the oil pump.

TSB #: **17-HC-001** Page 6 of 6