

Technical Service Bulletin

68 Parking aid malfunctions

68 17 20 2043850/3 January 11, 2017. Supersedes Technical Service Bulletin Group 68 number 16-19 dated December 12, 2016 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q7	2017	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised <i>Required Parts and Tools</i> (Clarifying statement added for part variations)
2	12/12/2016	Revised <i>Condition</i> (Additional photo for fuse location)
1	04/28/2016	Initial publication

The customer complains of one of the following conditions:

- The LED on the Park Assist button is flashing to indicate an error with the system, and an error message is displayed on the DIS (Figure 1 and Figure 2).
- Other symptoms may include loss of courtesy lamp operation or loss of glovebox illumination.
- Fuse ST5 SB15 may be blown (Figure 3).



Figure 1. LED on Park Assist button E266.

One or more of the following DTCs may be stored in the vehicle electrical system control module, J519 (address word 0009):

Technical Service Bulletin

- **DTC U141200** (Terminal 30-2 Open circuit)
- **DTC B14BB14** (Rear parking aid warning buzzer Open)
- **DTC B14BA14** (Front parking aid warning buzzer Open)
- **DTC B131411** (Supply voltage for interior lighting Short circuit to ground)
- **DTC B14BB12** (Rear parking aid warning buzzer Short circuit to B+)
- **DTC B14BA12** (Front parking aid warning buzzer Short circuit to B+)



Figure 2. Error on the DIS that appears for the customer.




Figure 3. Fuse location.

Technical Background

The sunvisor wiring or the wiring in the roof leading to one or both sunvisors is damaged (shorted to B+, shorted to ground or open) due to the wiring routing or damage from the sunvisor mounting screw.

Technical Service Bulletin

Production Solution

A production assembly instruction has been implemented to safeguard against damage during installation. Further improvements will include optimized routing of the sunvisor wiring in the visor mounting.

Service

Remove both sunvisors and inspect the wiring in the visor mounting as well as the wiring in the roof leading to the sunvisors:

- If the wiring in the visor is damaged, replace the sunvisor (Figure 4).
- If the wiring in the roof harness is damaged, it can be repaired using the VAS 1978B (Figure 5).
- If fuse ST5 SB15 is found to be blown, replace it.




Figure 4. Sunvisor wiring damage typically found after visor removal and inspection.

Technical Service Bulletin



Figure 5. Damage typically found on roof harness.



Technical Service Bulletin

Warranty


Claim Type:	<ul style="list-style-type: none"> • 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If vehicle is outside any warranty, this Technical Service Bulletin is informational only. 		
Service Number:	6823 (if replacing left sunvisor alone -or- both sunvisors) 6824 (if replacing right sunvisor alone)		
Damage Code:	0040		
Labor Operations:	If replacing one sunvisor:		
	Sunvisor left remove and reinstall	6823 1900	20 TU
	-or-		
	Sunvisor right remove and reinstall	6824 1900	20 TU
	If replacing both sunvisors:		
	Sunvisor left and right remove and reinstall	68 23 99 99	40 TU
	If repairing wiring in the roof harness:		
Repair roof electrical harness	9709 4156	70 TU	
Diagnostic Time:	GFF	0150 0000	Time stated on diagnostic protocol (Max 20 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU

Technical Service Bulletin

	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)
Claim Comment:	As per TSB #2043850/3

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
4M0857551X XXX	Sunvisor with illuminated mirror and cover - Left	1
4M0857552X XXX	Sunvisor with illuminated mirror and cover - Right	1
Please use VIN to determine color code and complete part number in ETKA before ordering.		
VAS 1978B	 <p>Wiring Harness Repair Set</p>	1

Additional Information

All parts and service references provided in this TSB (2043850) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in



Technical Service Bulletin

any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.