

#### 91 Rearview camera intermittently inoperative (DTC 2203)

91 17 00 2041430/4 January 11, 2017. Supersedes Technical Service Bulletin Group 91 number 16-48 dated June 23, 2016 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4	2013 - 2016	All	With rearview camera
A5	2013 - 2016	All	With rearview camera
A5 cabriolet	2013 - 2016	All	With rearview camera
A6	2014 - 2015	All	With rearview camera
A7	2014 - 2015	All	With rearview camera
A8	2013 - 2016	All	With rearview camera
Q3	2015 - 2016	All	With rearview camera
Q5	2013 - 2016	All	With rearview camera
Q7	2013 - 2015	All	With rearview camera

#### **Condition**

REVISION HISTORY			
Revision	Date	Purpose	
4	-	Revised header data (Added PR code)	
3	06/24/2016	Revised Service (Completely revised)	
2	10/15/2015	Revised Service (Changed step 3) Revised Warranty (Corrected TU for A5 cabriolet)	

- The customer complains that the rearview camera image is not displayed on the MMI display.
- **DTC 02203** (audio/video input 1) is logged in the rearview camera system control module, J772 (address word 006C) with one of the following fault symptoms:
  - 11 open circuit
  - 8 implausible signal



### **Technical Background**

An issue with the wiring harness may cause the condition.

### **Production Solution**

Not applicable.

#### **Service**

- Before proceeding, confirm that the DTC and one of the fault symptoms listed in the Condition are logged in the rearview camera system control module, J772 (address word 006C). If the DTC is not listed with one of the fault symptoms, this bulletin does not apply.
- 2. Check the wiring of the R189 reverse camera at connector T2az and T1y (Figure 1). Repair any loose connectors or pins, corrosion, or any other physical damage.






Figure 1. Check the wiring of the R189 reverse camera at connector T2az and T1y.

If no problems are found with the wiring or connections of the rear view camera, continue to step 3 to replace the rear view camera harness (Figure 2).



Figure 2. Reverse camera harness to be replaced.

3. Remove the reversing camera from vehicle. Follow applicable steps in the Elsa repair manual for the specific vehicle.




- 4. Remove the original harness from the reverse camera (Figure 3):
  - First, locate the locking tab on the reverse camera harness.
  - Next, using a small flat head screw driver, lift up on the locking tab.
  - Finally, snap the old locking tab off the defective harness to prevent reuse.



**Figure 3.** Locate locking tab (1), lift up on tab with screwdriver (2), snap tab off (3).

5. Carefully install the new reverse camera harness onto the camera assembly, as the harness can only be installed one way. The connector is keyed on both the camera and the electrical harness to prevent incorrect installation. Ensure they are correctly aligned during installation (Figure 4).



**Figure 4.** When installing the new reverse camera harness onto the camera assembly, ensure that the connectors are correctly aligned.

6. When the harness is fully secured to the camera, there will be an audible click sound. The sound is caused when the locking tab falls into place.



 Reinstall the completed reverse camera assembly, following instructions as outlined in the Elsa repair manual for the specific vehicle (Figure 5).



**Figure 5.** Completed reverse camera assembly with new electrical harness.

### **Warranty**

Claim Type:	<ul> <li>110 up to 48 Months/50,000 Miles.</li> <li>G10 for CPO Covered Vehicles – Verify Owner.</li> <li>If vehicle is outside any warranty, this Technical Service Bulletin is informational only.</li> </ul>		
Service Number:	9143		
Damage Code:	0040		
Labor Operations:	For all vehicles:		
	Central wiring harness repair	9709 41XX	See Elsa
	For A4, A5:		
	Rear trunk lid trim remove + reinstall	7087 1900	30 TU
	Back-up camera remove + reinstall	9143 1950	10 TU
	Back-up camera adjust	9143 1550	50 TU
	For allroad:		
	Tailgate trim panel remove + reinstall	7092 1900	40 TU



Back-up camera remove + reinstall	9143 1951	10 TU	
Back-up camera adjust	9143 1550	50 TU	
For A5 cabriolet:			
Rear trunk lid trim remove + reinstall	7087 1900	30 TU	
Back-up camera remove + reinstall	9143 1950	10 TU	
Back-up camera adjust	9143 1550	50 TU	
For A6:			
Rear trunk lid trim remove + reinstall	7087 1900	50 TU	
Back-up camera remove + reinstall	9143 1950	10 TU	
Back-up camera adjust	9143 1550	50 TU	
For A7:			
Back-up camera remove + reinstall	9143 1900	70 TU	
Back-up camera adjust	9143 1550	50 TU	
For A8:			
Back-up camera remove + reinstall	9143 1900	70 TU	
Back-up camera adjust	9143 1550	50 TU	
For Q3:			
Tailgate trim panel remove + reinstall	7092 1900	30 TU	



	Back-up camera remove + reinstall	9143 1950	10 TU	
	Back-up camera adjust	9143 1550	50 TU	
	For Q5:			
	Tailgate trim panel remove + reinstall	7092 1900	40 TU	
	Back-up camera remove + reinstall	9143 1950	10 TU	
	Back-up camera adjust	9143 1550	50 TU	
	For Q7:			
	Tailgate trim panel (top) remove + reinstall	7092 1905	20 TU	
	Tailgate trim panel (lower) remove + reinstall	7092 1950	40 TU	
	Back-up camera remove + reinstall	9143 1950	20 TU	
	Back-up camera adjust	9143 1550	50 TU	
Diagnostic Time:	GFF	0150 0000	Time stated on diagnostic protocol (Max 100 TU)	
	Road test prior to service procedure	No allowance	о ти	
	Road test after service procedure	No allowance	о ти	
	Technical diagnosis at dealer's discretion			
	(Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)			
Claim Comment:	As per TSB #2041430/4			



All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

#### **Required Parts and Tools**

Part Number	Part Description	Quantity
8K0971086D	Harness	1

#### **Additional Information**

All parts and service references provided in this TSB (2041430) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.