



SERVICE ACTION H018: AUXILIARY COOLANT PUMP - INCORRECT OPERATION

SERVICE BULLETIN

26-JUL-17

NO.: 6-360NAS

SEC.: GENERAL
INFORMATION

MKT.: CAN / USA

DESCRIPTION OF ISSUE

An issue has been identified on a limited number of Jaguar vehicles within the listed Affected Vehicle Range where the auxiliary coolant pump may run constantly when the engine is running and when the ignition is ON. The auxiliary coolant pump should operate only during an Auto Stop/Start event.

AFFECTED VEHICLE RANGE

F-PACE (X761; Ingenium I4 2.0L diesel)

Model Year: 2018

VIN: 240049-251521

XE (X760; Ingenium I4 2.0L diesel)

Model Year: 2018

VIN: P17307-P21958

XF (X250; Ingenium I4 2.0L diesel)

Model Year: 2018

VIN: Y53497-Y56259

Visit the Jaguar Business Network (JBN) website for a list of affected unsold vehicles (as of 26 July 2017).

SERVICE PROGRAM / REWORK ACTION

Retailers will update the Powertrain Control Module (PCM) with the latest software. There will be no charge to owners for this action under this program.

ACTION TO BE TAKEN

Check DDW to ensure that the vehicle is affected by this Program prior to undertaking any rework action.

Retailers are required to HOLD affected new vehicles that are within your control and refrain from releasing the vehicles for new vehicle sale pending completion of the rework action. Affected vehicles already in the hands of customers should be updated at the next available opportunity.

Refer to Technical Bulletin H018NAS, *Service Action: Auxiliary Coolant Pump - Incorrect Operation*, for detailed repair instructions.

PARTS

No parts required.

TOOLS

Refer to the Technical Bulletin referenced above for any required special tools.

WARRANTY

NOTE: check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action.

At the time of confirming a booking for vehicle repair, ensure that all outstanding Recall and Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed in one visit.

Warranty claims must be submitted quoting the Program Code together with the relevant Option Code. The SRO and parts information listed have been included for information only. The Option Code(s) that allows for the drive in/drive out allowance may only be claimed if the vehicle is brought into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times/prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **30 June 2019** closure date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS / SUNDRY CODE	QTY. / VALUE
H018	B	PCM - Configure existing	86.99.26	0.20	-	-
H018	C	PCM - Configure existing	86.99.26	0.20	-	-
		Drive in/drive out	10.10.10	0.20	-	-
H018	D	PCM - Configure existing	86.99.26	0.20	-	-
		Transit mode - Engage	86.98.50	0.10	-	-
H018	E	PCM - Configure existing	86.99.26	0.20	-	-
		Transit mode - Engage	86.98.50	0.10	-	-
		Drive in/drive out	10.10.10	0.20	-	-

Normal Warranty policies and procedures apply.