



# Technical Bulletin

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
e-Golf	2015-2016	All	All	All	All
e-Golf	2017	All	All	AU_HW000001	AU_HW950059

## Condition

**87 17 04** April 18, 2017 **2040184** Supersedes Technical Bulletin V871703 dated March 9, 2017 to add additional fault P0CEB00: Coolant pump for low temperature circuit.

**Climatronic with Heat Pump - Sporadically Too Low Heating or Cooling Performance**



**Note:**

This bulletin must be read in its entirety before performing the procedure.

## Technical Background

The customer may complain that the cabin heating or cooling output is insufficient.

Software-related deviation in thermal management control unit.

- The vehicle interior is sporadically not sufficiently heated or cooled.
- The heating or cooling performance is sporadically too low.

The following DTCs can be logged in the thermal management control module **-J1024-**:

DTC	Description	Event Code
P1C1A00	Shut-off valve 1 for refrigerant, mechanical fault, active/static	4135
P1C3200	Shut-off valve 4 for refrigerant, mechanical fault, active/static	4136 4121
P1C3A00	Shut-off valve 5 for refrigerant, mechanical fault, active/static	4137
P1C0200	Expansion valve 1 for refrigerant, mechanical fault, active/static	4138



# Technical Bulletin

P1C0A00	Expansion valve 2 for refrigerant, mechanical fault, active/static	4139
P1C1200	Expansion valve 3 for refrigerant, mechanical fault, active/static	4140
P1C1E00	Shut-off valve 1 for refrigerant, implausible signal passive/sporadic	59082
P1C3600	Shut-off valve 4 for refrigerant, implausible signal passive/sporadic	59106
<b>P0CEB00</b>	<b>Coolant pump for low temperature circuit, short circuit to earth, passive / sporadic</b>	<b>-</b>
U112300	Data bus, received error value, active/static	36919
U112300	Data bus, received error value, active/static	36921
U112300	Data bus, received error value, active/static	37009
U112300	Data bus, received error value, active/static	37051

## Production Solution

Thermal Management Software 0203 in production AU\_HW950059.



# Technical Bulletin

---

## Service

### Procedure:

1. There are two procedures required to complete this repair.
  - a. Update software of thermal management control unit
  - b. Perform initial run of air conditioner compressor



### Note:

If the software of the address C5 Thermal Management is already at 0203 (or higher) this bulletin does not apply, further system diagnosis is required.



### Tip:

To Update-Programming using SVM, **review and follow** instructions in **Technical Bulletin Instance 2014603** "Software Version Management".

The SVM Process must be completed in its entirety so the database receives the update confirmation response. A warranty claim may not be reimbursed if there is no confirmation response to support the claim.

- **ODIS tester:** The ODIS tester patch [version 4.0.0 and the baseline version 2.33.3 or higher](#) must be installed.
- Make sure that a battery charger is connected to the vehicle battery.
- Make sure that during the software update no electro-magnetic radiation sources (for example, mobile phones or cordless phones) are used in or near the vehicle.
- A cable connection between the ODIS tester and the vehicle must be used. When using a Bluetooth connection (diagnostic tool) the software update may fail.
- A cable connection between the ODIS tester and your workshop network must be used. When using a WIFI connection (diagnostic tool) the software update may fail.
- During the software update switch the hazard warning lights on to ensure a constant CAN data bus activity of the vehicle.



### Note:

Prior to launching the ODIS service diagnostic applications and starting control module update process, confirm Date/Time & Time Zone.

The Windows date/time and time zone settings are used by the diagnostic software as a component of the diagnostic logs submitted for warranty purposes. If the date/time and time zone are incorrect on submitted diagnostic logs, warranty claim reimbursement may be questioned and/or delayed.

Ensure date/time etc. settings are correct as follows:



# Technical Bulletin

1. From the Windows desktop toolbar, double click on the local time indicator (typically found in the lower right corner of the desktop).
2. Use the tabs to ensure the current date/time, and time zone applicable to your location is set correctly.

## A. Update software of thermal management control module

Using software version management (SVM), update the software of the thermal management control module (diagnosis address C5) according to the table below.

- To perform the software update, after the full vehicle scan, click on the “Special Functions” tab and then select “Adapting Software”.
- Follow the on screen prompts to update the thermal management control module using the SVM Unit code as listed in the tables below:

Model	Old Part Number	Old Software Version	New Part Number	New Software Version	SVM Unit Code	Online
e-Golf	5GE907458	0101	5GE907458B	0203 (or higher)	3C58	CW07/2017
e-Golf	5GE907458	0103	5GE907458B	0203 (or higher)	3C58	CW07/2017
e-Golf	5GE907458	0105	5GE907458B	0203 (or higher)	3C58	CW07/2017
e-Golf	5GE907458	0107	5GE907458B	0203 (or higher)	3C58	CW07/2017
e-Golf	5GE907458	0108	5GE907458B	0203 (or higher)	3C58	CW07/2017
e-Golf	5GE907458A	0109	5GE907458B	0203 (or higher)	3C58	CW07/2017
e-Golf	5GE907458B	0202	5GE907458C	0203 (or higher)	3C58	CW07/2017



# Technical Bulletin

---



## NOTE:

During the software flash process, it is normal for the sound generator to output a loud continuous noise. This sound will stop once the flash process is complete.



## WARNING:

Radiator Fan(s) may cycle ON high speed during the update process! There is a serious risk that personal injury may result if contact is made with spinning fan blades. Keep hands and all objects away from Radiator Fan(s) during Update Process!

- After the update is complete check and erase all DTCs before performing the initial run procedure.

## B. Perform initial run of air conditioner compressor



## NOTE:

After the software update is complete, an initial run of the compressor must be carried out according to the Guided Functions. The start switch must be ON, brake pedal depressed and electric motor indicator in the instrument panel in READY status (Figure 1). The initial run of the compressor will not complete without READY status illuminated.



# Technical Bulletin

---



Figure 1



# Technical Bulletin

## Warranty

<b>To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual <sup>1)</sup></b>					
Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
e-Golf	2015-2016	All	All	All	All
e-Golf	2017	All	All	AU_HW000001	AU_HW950059
<b>SAGA Coding</b>					
<b>Claim Type:</b>	<b>Use applicable Claim Type <sup>1)</sup></b>				
<b>Service Number:</b>	<b>Damage Code</b>	<b>HST</b>		<b>Damage Location (Depends on Service No.)</b>	
8848	0039	--		Use applicable when indicated in Elsa (L/R)	
<b>Parts Manufacturer</b>	<b>e-Golf</b>			<b>WWO <sup>2)</sup></b>	
<b>Labor Operation <sup>3)</sup>: Charge Battery</b>			27068950 = 10 TU		
<b>Labor Operation <sup>3)</sup>: Update Programming</b>			See GFF Time expenditure		
<b>Causal Part: Select Labor Operation</b>			01500000		
<b>Diagnostic Time <sup>4)</sup></b>					
<b>GFF Time expenditure</b>	01500000 = Actual GFF printout - 60 TU max.			Yes	
<b>Road Test</b>	01210002 = 00 TU 01210004 = 00 TU			NO	
<b>Technical Diagnosis</b>	01320000 = 00 TU max.			NO	
<b>Claim Comment: Input "As per Technical Bulletin 2040184" in comment section of Warranty Claim.</b>					
<b><sup>1)</sup> Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only</b>					



# Technical Bulletin

- 2) Code per warranty vendor code policy.
- 3) Labor Time Units (TUs) are subject to change with ELSA updates.
- 4) Documentation required per Warranty Policies and Procedures Manual.

## Required Parts and Tools

No special parts required.

Tool Description	Tool No:
Midtronics Battery Tester/Charger	InCharge 940 (INC-940) or GRX3000VAS
VAS Diagnostic Tool	VAS 6150/X & VAS 6160/X and ODIS Service with: current online updates

## Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.

Document Control Revision Table			
Instance Number	Published Date	Version Number	Reason For Update
2040184/7	4/18/17	V871704	To Update fault table.
2040184/1	3/26/15	V871503	Original publication.