



HA16-008a

Reference:

Date: February 3, 2017

2014 – 2017 VERSA NOTE: POOR HEATER PERFORMANCE WITH AMBIENT TEMPERATURE BELOW -20°C (-4°F)

NTB16-106a

This bulletin has been amended throughout. Discard previous versions of this bulletin.

APPLIED VEHICLE: 2014 – 2017 Versa NOTE (E12) 2014 – 2016: ALL APPLIED VIN and DATE: 2017: Vehicles built before 3N1CE2CP(*)HL 351933 and October 25, 2016

IF YOU CONFIRM

Classification:

The customer reports the HVAC system does not produce enough heat (poor heater performance).

and

The issue occurs with ambient temperatures below -20°C (-4°F),

and

The engine thermostat is operating correctly.

ACTION

- 1. Install a heater thermostat per the **SERVICE PROCEDURE** in this bulletin.
- 2. Refer to step 6 in the **Reprogram ECM** section of the **SERVICE PROCEDURE** to confirm reprogramming in needed.

NOTE: Reprogramming does not apply to 2016 and 2017 model year Versa NOTE.

3. Reprogram the ECM, if needed.

IMPORTANT: The purpose of **ACTION** (above) is to give you a quick idea of the work you will be performing. You MUST closely follow the entire SERVICE PROCEDURE as it contains information that is essential to successfully completing this repair.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

SERVICE PROCEDURE

Heater Thermostat – Remove and Install

CAUTION: Use fender covers or suitable covering on painted surfaces and all other surrounding exterior parts when working in the engine area.

- 1. Set the vehicle on a lift.
- 2. Drain the engine coolant.
 - Refer to the Electronic Service Manual (ESM), section CO-Engine Cooling System, for cooling system draining information.

NOTE: The coolant will be reused. Catch and store the coolant in a suitable clean container.

IMPORTANT: Follow all **WARNINGS**, **CAUTIONS**, and **NOTES** in the ESM when working on an engine, transmission, cooling system, and its surrounding areas.

3. Unclamp, and then remove the water hose from the CVT oil warmer (see Figure 1a and 2a).



Figure 1a




Figure 2a




Figure 3a

4. Unbolt, and then unhook the bracket (see Figure 3a).

- 5. Lower the vehicle, and then remove the air cleaner and air duct as an assembly (see Figure 4a).
 - Refer to the ESM, section **EM**-**Engine Mechanical**, for air cleaner and air duct removal information.



Figure 4a

- Unfasten, or cut and unfasten the clip (see Figure 5a).
 NOTE: A clip comes with the replacement (new) part.
- 7. Unclamp the hose, and then remove the hose and bracket as an assembly (see Figure 5a).




Figure 5a

- 8. Install the two hoses and heater thermostat as an assembly in reverse order of water hose removal.
 - Use two (2) new clamps, one at each end.
- 9. Refill the cooling system.
 - Refer to the ESM, section **CO-Engine Cooling System**, for cooling system refilling procedure.

Reprogram ECM

NOTE:

- Reprogramming in this bulletin does not apply to 2016-2017 model year Versa NOTE.
- Most instructions for reprogramming with CONSULT-III plus (C-III plus) are displayed on the CONSULT PC screen.
- If you are not familiar with the reprogramming procedure, *click here*. This will link you to the "CONSULT-III plus (C-III plus) ECM Reprogramming" general procedure.
- Take the vehicle for a 10 minute drive in order to meet the following Idle Air Volume Learn (IAVL) conditions:
 - Engine coolant temperature: 70 -100°C (158 - 212°F)
 - Battery voltage: More than 12.9V (At idle)
 - Transmission: Warmed up





• After reprogramming is complete, you will be required to perform Idle Air Volume Learn. The above condition are required for Idle Air Volume Learn to complete.

CAUTION:

- Connect the GR8 to the 12V battery and select ECM Power Supply Mode. If the vehicle battery voltage goes below <u>12.0V or above 15.5V</u> during reprogramming, <u>the ECM may be damaged</u>.
- Be sure to turn OFF all vehicle electrical loads.
 If a vehicle electrical load remains ON, <u>the ECM may be damaged</u>.
- Be sure to connect the AC Adapter. If the CONSULT PC battery voltage drops during reprogramming, the process will be interrupted and <u>the ECM may be damaged</u>.
- Turn off all external Bluetooth[®] devices (e.g., cell phones, printers, etc.) within range of the CONSULT PC and the plus VI. If Bluetooth[®] signal waves are within range of the CONSULT PC during reprogramming, reprogramming may be interrupted and <u>the ECM may be damaged</u>.

- 1. Connect the CONSULT PC to the vehicle to begin the reprogramming procedure.
- 2 Start C-III plus.
- 3. Wait for the plus VI to be recognized.
 - The serial number will display when the plus VI is recognized.
- 4. Select Re/programming, Configuration.

	CONSC	ne i - in pius ver. viz		venicie	country . 0.3.A.	
	Back	Home Print	Screen Screen Capture Mode	rded Help		
	Conne	ction Status -		Diagnosis Menu		
Step 3:		Serial No.	Status	Diagnosis (One System)	
plus VI is	VI	2300727				
recognized			Normal Mode/Wireless connection	Diagnosis ((All Systems)	
	м	-	\bigotimes			Step
			No connection	Selprogram	nming, Configuration	4
	30	Select VI/MI		Immobilizer	r	
	Applica	tion Setting				
	SUB	Sub mode	Language Setting	Maintenanc	ce	
	87	VDR				
			Figu	ure 1		

5. Follow the on-screen instructions and navigate C-III plus to the screen shown in Figure 2 on the next page.

- 6. When you get to the screen shown in Figure 2, confirm this bulletin applies as follows.
 - A. Find the ECM **Part Number** and write it on the repair order.

NOTE: This is the <u>current</u> ECM Part Number (P/N).

CONSULT-III plus Ver VIN	Vehicle :	Country : U.S.A.						
Back Back Print Screen Capture	Massurement Mode Recorded Data	× 🖿 📃 🔀						
Configuration	ation Selection Save ECU Data	717						
Save ECU Data								
	e current part number as listed below to CONSULT. n by selecting suitable operation log. Operation log is era	ised						
File Label	200000000000000000000000000000000000000							
Operation	REPROGRAMMING							
System								
Part Number 6A: <u>Cu</u> ECM								
Vehicle	xxxxxxxxxxxxxxxxxxx							
VIN	xxxxxxxxxxxxxxxxxx							
Date	11/1/201× 1:22:16 AM	Save						

Figure 2

- B. Compare the P/N you wrote down to the numbers in the Current ECM Part Number column in Table A below.
 - If there is a <u>match</u>, continue with the reprogramming procedure.
 - If there is <u>not a match</u>, reprogramming is not needed.

Table A	
MODEL YEAR	CURRENT ECM PART NUMBER: 23710-
2014	3VB3B, 3VB3C, 3VB3D, 3VB3E 3VB4B, 3VB4C, 3VB4D, 3VB4E 3VB5B, 3VB5C, 3VB5D, 3VB5E
2015	9MB2A, 9MB3A, 9MB4A, 9MB5A
2016-2017	Reprogramming not needed

7. Follow the on-screen instructions to navigate C-III plus and reprogram the ECM.

NOTE:

- In some cases, more than one new P/N for reprogramming is available.
 - > If there is more than one new P/N, the screen in Figure 3 displays.
 - Select and use the reprogramming option that <u>does not</u> have the message "Caution! Use ONLY with NTBXX-XXX".
- If you get this screen and it is <u>blank</u> (no reprogramming listed), it means there is no reprogramming available for this vehicle.

CONSULT-III plus Ver.	VIN:	Vehicle :	Country : U.S.A.
Back Prir	t Screen Capture	Percerded u.v.	🚔 🌠 🗙 💻 🔜 🔀
Re/programming, Configuration	Precaution	Select Program Data	Confirm Vehicle Condition 9/11
Select Program Data			
		elow. firm the vehicle selection, VIN and	
System	ENGINE		
Current Part Number	Part Number After Rep	ro/programming Othe	r Information
xxxxxx-xxxxxx	XXXXXX-XXXXXXX	xxxxxxxxxxx	xxxxxxxxxxxx
XXXXXX-XXXXXXX	X00000X-X00000X	000000000	000000000000000000000000000000000000000
		0.	Next

Figure 3

8. When the screen in Figure 4 displays, reprogramming is complete.

NOTE: If the screen in Figure 4 does <u>not</u> display (indicating that reprogramming did <u>not</u> complete), refer to the information on the next page.

- 9. Disconnect the battery charger from the vehicle.
- 10. Select Next.




Figure 4

NOTE:

- In the next steps, starting on page 10, you will perform Throttle Valve Closed Position, Idle Air Volume Learn, Accelerator Closed Position, and DTC erase.
- These operations are required before C-III plus will provide the final reprogramming confirmation report.

Do not disconnect plus VI or shut down Consult III plus if reprogramming does not complete.

If reprogramming does <u>not</u> complete and the "!?" icon displays as shown in Figure 5:

- Check battery voltage (12.0–15.5 V).
- Ignition is ON, engine OFF.
- External Bluetooth[®] devices are OFF.
- All electrical loads are OFF.
- Select <u>retry</u> and follow the on screen instructions.
- <u>"Retry" may not go through on</u> <u>first attempt and can be</u> <u>selected more than once</u>.

	VN Ushida	Ecunty : Japan
Back Home Print Screen	Schen Massesters Recorded Data	
responsering	Transfer Data Corline Resul	1313
Confirm Result		
Reprogramming or programming is r operation on his ECU. Touch "Reby" to retry reprogrammin	iot completed propertly, but you can retry reprogr g or programming.	xogramming
Part number after Reprog/programming	- 20102 10010	-
Part number before Reprog/programming		k
	0.0010.001	
Vehicle		
VIN	- DEFENSION IN IN	
VIN		Retry
VIN System		Roty

Figure 5

If reprogramming does <u>not</u> complete and the "X" icon displays as shown in Figure 6:

- Check battery voltage (12.0 – 15.5 V).
- CONSULT A/C adapter is plugged in.
- Ignition is ON, engine OFF.
- Transmission is in Park.
- All C-III plus / VI cables are securely connected.
- All C-III plus updates are installed.
- Select <u>Home</u>, and restart the reprogram procedure from the beginning.

CONSULT-ILIDUS Ver	MN	Vehicle : QASHQAI	0	Country : Japan
Bark Hone Print Screek	Kiten Measurement	Recorded Holo 42.7	N	• 🗕 🔀
S configition	Transfer Data	Confirm Result		9/9
Confirm Result				
Reprogramming is not completed prop Print this screen as needed. Confirm (with precedure. -Restart CONSULT with disconnecting	CONSULT version, IG		ition and etc	
Part number after Reprog/programming		21 122 10000		
Current part number		21/82 10/0301		
Vehicle				
VIN				
System				
Date				
Information				

Figure 6

11. Follow the on-screen instructions to perform the following:

- Throttle Valve Closed Position
- Idle Air Volume Learn (IAVL)

NOTE:

- > Listed below are common conditions required for IAVL to complete.
- If IAVL does not complete within a few minutes, a condition may be out of range.
- Refer to the appropriate ESM for specific conditions required for the vehicle you are working on.
 - Engine coolant temperature: 70 -100° C (158 212°F)
 - Battery voltage: More than 12.9V (At idle)
 - o Selector lever: P or N
 - Electric load switch: OFF (Air conditioner, headlamp, rear window defogger)
 - Steering wheel: Neutral (Straight-ahead position)
 - Vehicle speed: Stopped
 - o Transmission: Warmed up
- Accelerator Pedal Close Position Learning
- Erase DTCs

Continue to the next page.

- 12. When the entire reprogramming process is complete, the screen in Figure 7 will display.
- 13. Verify the before and after part numbers are different.
- 14. Print a copy of this screen (Figure 7) and attach it to the repair order for warranty documentation.
- 15. Select Confirm.


CONSULT-III plus Ver VIN	: Vehicle :		Country : U.S.A.		
Back Home Print Screen Capture	Messurement Mode	14.3V VI	× 🗭 📃 🔀		
Configuration	ase All DTCs Print Result / Operation Complete		18/18		
Print Result / Operation Complete					
All tasks are completed. Confirm LAN acce In case CONSULT can NOT immediately ac temporally storage of this page. Touch "Sc Data Folder" on desk top, and open the fold	cess to LAN or printer, Screen Capture fun reen Capture'', and save it. Screen capture				
Part number after Reprog/programming	Step 23710	<u>.</u>			
Part number before Reprog/programming	13 23710	-			
Vehicle	*****				
VIN	******				
System	ENGINE		Print		Step 14
Date	14/2/2014 0.40.01 4	м		 	14
		1/1	Confirm		Step 15
	F :				

Figure 7

- 16. Close C-III plus.
- 17. Turn the ignition OFF.
- 18. Disconnect the plus VI from the vehicle.

PARTS INFORMATION

DESCRIPTION	P/N	QUANTITY
THERMOSTAT ASSY (heater thermostat with 2 hoses & 2 clamps)	21200-3AA4A	1
CLAMP (hose clamp)	16439-7S01D	2



CLAIMS INFORMATION

Submit a Primary Part (PP) type claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Replace Thermostat and Water Hose	(1)	CD40AA	ZE	32	(2)

(1) Reference FAST and use the Water Hose part number (14055-****) as the PFP.

(2) Reference the current Nissan Warranty Flat Rate Manual and use the indicated FRT.

And if ECM Reprogramming applies on the same line:

DESCRIPTION	OP CODE	SYM	DIA	FRT
Reprogram ECM (1)	DE97AA	ZE	32	(2) (3)

(1) Does not apply to 2016-2017 model year Versa NOTE.

(2) Reference the current Nissan Warranty Flat Rate Manual and use the indicated FRT.

(3) FRT allows adequate time to access DTC codes and reprogram ECM. No other diagnostic procedures subsequently required. Do NOT claim any Diagnostic Op Codes with this claim.