

NUMBER: 23-039-17

GROUP: 23 - Body

DATE: September 2, 2017

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

SUBJECT:

Rear Door Fixed Glass Cover is Loose

OVERVIEW:

This bulletin involves rework to the rear door fixed glass cover trim.

MODELS:

2016 - 2017	(D2)	RAM 3500 Pickup
2016 - 2017	(DD)	RAM 3500 Cab Chassis
2016 - 2017	(DF)	RAM 3500 <10K LB Cab Chassis
2016 - 2017	(DJ)	RAM 2500 Pickup
2016 - 2017	(DP)	RAM 4500/5500 Cab Chassis
2016 - 2017	(DS)	RAM 1500 Pickup
2016 - 2017	(DX)	RAM Truck (Mexico)
2016 - 2017	(DS)	RAM 1500 Pickup

NOTE: This bulletin applies to vehicles within the following markets/countries: NAFTA.

NOTE: This bulletin applies to vehicles built on or before September 01, 2017 (MDH 0901XX).

23-039-17 -2-

SYMPTOM/CONDITION:

The customer may notice the glass cover trim is loose or shows a gap on either of the rear door (Fig. 1) .



Fig. 1
Gap Identified at Door

DIAGNOSIS:

If the customer describes the symptom/condition listed above, perform the Repair Procedure.

SPECIAL TOOLS/EQUIPMENT REQUIRED:

0 4755	-	
1C-4755	Trim Stick	
U-T1 00	IIIII Olick	

REPAIR PROCEDURE:

1. Remove the rear door glass fixed trim (Fig. 2) using trim stick C-4755 or equivalent, release the upper trim bezel.




Fig. 2 Trim at Door

1 - Door Glass Trim

23-039-17 -4-

2. After the trim piece is removed use a sharp knife or equivalent to remove the forward/short locator (Fig. 3), remove the locator down to the substrate surface.

NOTE: Do not remove or modify the rear/long locator (Fig. 3).




Fig. 3
Short Locator to be Removed

- 1 Locator to be Removed
- 2 Do Not Remove this Locator
- 3. Install the rear door glass fixed trim (Fig. 2) .

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
23-20-22-9H	Door, Glass Cover Trim - Rework/Modify Locator (1 - Semi-Skilled)	6 - Electrical and Body Systems	0.2 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------