



# Preliminary Information

PIP5493D Misfire with DTC's P0300, P0301-P0306

## Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	LaCrosse	2017 - 2018	All	All	3.6 LGX	All
Cadillac	ATS	2016 - 2018	All	All	3.6 LGX	All
Cadillac	CT6	2016 - 2018	All	All	3.0 LGW, 3.6 LGX	All
Cadillac	CTS	2016 - 2018	All	All	3.6 LGX	All
Cadillac	XT5	2017 - 2018	All	All	3.6 LGX	All
Chevrolet	Camaro	2016 - 2018	All	All	3.6 LGX	All
Chevrolet	Colorado	2017 - 2018	All	All	3.6 LGZ	All
GMC	Acadia	2017 - 2018	All	All	3.6 LGX	All
GMC	Canyon	2017 - 2018	All	All	3.6 LGZ	All
Involved Region or Country	North America					
Condition	Some customers may comment on a MIL light illuminated. During diagnosis a technician may find DTC P0300 (Engine Misfire Detected) and/or a specific cylinder DTC such as P0300, P0301-P0306 This code may be active or stored in history.					
Cause	Multiple causes depending on vehicle configuration.					

## Correction:

Verify the vehicle has the latest ECM calibration.

If a new calibration is available, reprogram the ECM and reevaluate the condition.

If code(s) do not return and no condition is present then return vehicle to customer.

If vehicle has the latest ECM calibration refer below for next steps.

1) Perform normal eSI diagnostics testing all spark and fuel components for issues. (Coil grounds and wiring, injector concerns, spark plugs, etc)


If no concerns are found following ESI then follow this PI for repair.

2) Inspect for broken or dislodged SRFFs (rockers arms) per the pictures below.


While inspecting the rockers it will be necessary to rotate the engine over by hand to ensure that the rockers are opening the valves.

**NOTE: Camshaft carrier assembly removal may be necessary to fully inspect the rockers and SRFF's.**

If any one of the SRFF's are damaged it will be necessary to replace all four on the affected cylinder.



3) Remove the camshaft actuators on the bank that is misfiring and inspect the end of the camshafts and the pin in the actuators for being bent example shown below.



- 4) If any broken parts are found during inspection replace all damaged parts. It will also be necessary to replace the AFM OCV in the camshaft cover for both banks.
- 5) If vehicle was built before November 1, 2017 Call TAC to get sorted parts sent to replace the effected exhaust shla's/ lifters on the cylinder that was misfiring.

**Warranty Information**

For vehicles repaired under warranty, use the current labor time for the actual repair made.

**Version History**

Version	5
Modified	6/7/2017 Update to add Model Year in Correction. 6/29/2017 Update to add further direction with picture and correct engine description. 8/2/2017 Update to add new directions and administrative details. 10/30/2017 update to add model year and directions and pictures.



© 2016 General Motors. All Rights Reserved.