

HVAC Blower Motor Continuous Operation With Ignition OFF

Service

Category Vehicle Interior

Section Heating/Air Conditioning Market USA



Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION	
2018	C-HR		

Introduction

Some 2018 model year C-HR vehicles may exhibit a condition where the HVAC blower motor will continue to operate when the ignition is turned OFF and the blower motor switch is in any ON position. Other symptoms of this condition can include the A/C not blowing cool air as the A/C amplifier will not go into sleep mode. Follow the Repair Procedure in this bulletin to address this condition.

Production Change Information

This bulletin applies to vehicles produced **BEFORE** the Production Change Effective VIN shown below.

MODEL	PLANT	PRODUCTION CHANGE EFFECTIVE VIN	
C-HR	TMMT	NMTKHMBX#JR032815	

Warranty Information

OP CODE	E DESCRIPTION		OFP	T1	T2
AC1701	1701 Reprogram A/C Amplifier		88650-F4060	82	71

APPLICABLE WARRANTY

- This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

TOYOTA T-SB-0299-17 October 17, 2017 Page 2 of 3

HVAC Blower Motor Continuous Operation With Ignition OFF

Required Tools & Equipment

REQUIRED EQUIPMENT	SUPPLIER	PART NUMBER	QTY
Techstream 2.0*		TS2UNIT	
Techstream Lite	ADE	TSLITEPDLR01	1
Techstream Lite (Green Cable)		TSLP2DLR01	

^{*} Essential SST.

NOTE

- Only ONE of the Techstream units listed above is required.
- Software version 12.20.024 or later is required.
- Additional Techstream units may be ordered by calling Approved Dealer Equipment (ADE) at 1-800-368-6787.
- Use Techstream or an approved J2534 interface to perform flash reprogramming updates. Visit <u>techinfo.toyota.com</u> for more information regarding J2534 reprogramming.

SPECIAL SERVICE TOOLS (SST)	PART NUMBER	QTY
GR8 Battery Diagnostic Station*	00002-MCGR8	1

^{*} Essential SST.

NOTE

Additional SSTs may be ordered by calling 1-800-933-8335.

Calibration Information

MODEL	ECU	CALIBRATION ID		
		PREVIOUS	NEW	
C-HR	A/C Amplifier	8865FF402003	8865FF402101	

Repair Procedure

1. Confirm the condition.

Does the HVAC blower motor continue to operate when the blower motor switch is in ANY ON position with the ignition OFF?

- YES Continue to step 2.
- NO This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.

TOYOTA T-SB-0299-17 October 17, 2017 Page 3 of 3

HVAC Blower Motor Continuous Operation With Ignition OFF

Repair Procedure (Continued)

Flash reprogram the A/C amplifier assembly.
Follow the procedure outlined in Service Bulletin <u>T-SB-0134-16</u>, "Techstream ECU Flash Reprogramming Procedure," and flash the A/C amplifier with the NEW calibration file update.

NOTE

The GR8 Battery Diagnostic Station MUST be used in Power Supply Mode to maintain battery voltage above 11.4V while flash reprogramming the A/C amplifier.

NOTICE

- Damage to the A/C amplifier may occur if the correct battery charge mode setting is NOT used.
- Power Supply Mode is used to maintain battery voltage at 13.5V while flash reprogramming.
- For details on how to use the GR8 Battery Diagnostic Station, refer to the "GR8 Instruction Manual" located on the Technical Information System (TIS): Diagnostics Tools & Equipment Battery Diagnostics.
- 3. Confirm the blower motor stops operating with the blower motor switch in ANY ON position with the ignition OFF.