

**TECHNICAL SERVICE BULLETIN****17-2217****Message In IPC Unable To Change Drive Mode - Illuminated MIL - Diagnostic Trouble Code (DTC) P26FE – Built On Or Before 02-Aug-2017**26 October
2017

This bulletin supersedes 17-2063. Reason for update: New Part/Procedure For Same Condition

This bulletin supersedes 17-2160. Reason for update: New Part/Procedure For Same Condition

Model:

Ford 2016-2017 Focus

Summary

This article supersedes TSB 17-2160 to update the labor operation.

Issue: Some 2016-2017 Focus RS vehicles built on or before 02-Aug-2017 may exhibit an Unable to Change Drive Mode message in the instrument panel cluster (IPC) and/or an illuminated malfunction indicator lamp (MIL) with DTC P26FE stored in the powertrain control module (PCM) memory.

Action: Reprogram the PCM to the latest calibration using Integrated Diagnostic System (IDS) or Ford J2534 Diagnostic Software (FJDS) release 106.04 or higher. Make sure you are connected to the internet when entering module programming to obtain the latest updates. Calibration files may also be obtained at www.motorcraftservice.com.

Warranty Status: Eligible Under Provisions Of New Vehicle Limited Warranty Coverage Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

Description	Operation No.	Time
2016-2017 Focus RS: Retrieve DTCs And Reprogram The PCM (Do Not Use With Any Other Labor Operations)	172217A	0.3

Repair/Claim Coding

Causal Part:	Recalem
Condition Code:	04

© 2017 Ford Motor Company

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.