

LTB01029NAS1

TECHNICAL BULLETIN

19 JUL 2017



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

SECTION:

206-03 Front Disc Brake

SUBJECT/CONCERN:

Noise From Front Brakes

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
Discovery Sport (LC)	2015 Onwards	500301 Onwards	Halewood
Range Rover Evoque (LV)	2016 Onwards	077912 Onwards	Halewood

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:**SITUATION:**

A noise from front brake system during light brake pedal application may be evident, mostly from cold start in colder ambient temperatures and typically does not re-occur after the brakes have warmed up.

CAUSE:

This may be caused by lower ambient temperatures cause the friction levels at the front brake pad to disc interface to increase and producing a high frequency noise during light braking applications.

ACTION:

Should a Customer express this concern, follow the Service Instruction below.

PARTS:

PART NUMBER	DESCRIPTION	QUANTITY:
LR094236	Brake Pad Set - Front	1

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:

NOTES:

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.
- The JLR Claims Submission System requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
-------------	-----	--------------	----------------	-------------

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Shoes/Pads - Front - Set - Renew - Discovery Sport (L550)	70.40.02	0.7	42	LR072681
Shoes/Pads - Front - Set - Renew - Range Rover Evoque (L538)	70.40.02	0.6	42	LR072681

NOTE:

Normal Warranty procedures apply.

SERVICE INSTRUCTION:

-
- 1 Replace the front brake pads; see TOPIx Workshop Manual section:
 - **Discovery Sport [L550]** - 206-03 Front Disc Brake - Brake Pads
 - **Range Rover Evoque [L538]** - 206-03 Front Disc Brake - Brake Pads AWD