LTB00631NAS5 TECHNICAL BULLETIN 22 SEP 2017



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

This reissue replaces all previous versions. Please destroy all previous versions.

Changes are highlighted in blue

SECTION:

501-14: Handles, Locks, Latches and Entry Systems

SUBJECT/CONCERN:

Smart Key Handset - Lower-Level Service Repair

https://topix.landrover.jlrext.com/topix/service/document/822532

10/4/2017

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
LR2 (LF)	2013-2015	303399-439912	Halewood
LR4 (LA)	2012-2016	582668-847658	Solihull
Discovery Sport (LC)	2015 Onwards	500429 Onwards	Halewood
Range Rover Evoque (LV)	2012	000447-000695	Halewood
Range Rover Sport (LS)	2012-2013	709788-814146	Solihull
Range Rover Evoque (LV)	2012-2015	600018-999999	Halewood
Range Rover Evoque (LV)	2015 Onwards	000051 Onwards	Halewood
Range Rover Sport (LW)	2014	001154-001205	Solihull
Range Rover Sport (LW)	2014-2015	300003-399997	Solihull
Range Rover Sport (LW)	2014-2016	500023-599874	Solihull
Range Rover Sport (LW)	2014 Onwards	600009 Onwards	Solihull
Range Rover Sport (LW)	2015 Onwards	100000 Onwards	Solihull
Range Rover (LG)	2013 Onwards	001204 Onwards	Solihull

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:

SITUATION:

The face of the Smart key handset may peel away from the handset main body or the handset case may be bulging.

CAUSE:

This may be caused by the handset manufacturing process.

NOTE:

Replace only the affected Smart key handset; it is not necessary to replace both handsets. All customer handsets must match after the conclusion of the repair.

ACTION:

Should the customer express this concern, follow the Workshop Procedure outlined below.

PARTS:

NOTE:

One (1) kit required per handset.

PART NUMBER	DESCRIPTION	QUANTITY:
LR078922	Smart key kit - Gloss finish - 'LAND ROVER' - LR2 (L359), LR4 (L319), Discovery Sport (L550)	1
LR059383	Smart key kit - Gloss finish - 'RANGE ROVER' - Range Rover Evoque (L538), Range Rover Sport (L322, L494), Range Rover (L405)	1
LR078921	Smart key kit - Matte finish - 'RANGE ROVER' - Range Rover Evoque (L538), Range Rover Sport (L322, L494), Range Rover(L405)	1

WARRANTY:

NOTE:

SRO time covers one (1) handset (may be used per handset repaired when applicable).

NOTES:

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.
- The JLR Claims Submission System requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Casing - 'LAND ROVER' Smart key - Renew - One	86 77 36	0.1	49	LR029695
Casing - 'RANGE ROVER' Smart key - Renew - One	86 77 36	0.1	49	LR027451

NOTE:

Normal Warranty procedures apply.

WORKSHOP PROCEDURE:

NOTES:

Refer to SSM70798, 'Smart key low level repair, animation of process', to view the animation file.


 Replace only the affected Smart key handset; it is not necessary to replace all handsets. All customer handsets must match after the conclusion of the repair.

Step 1: Range Rover Evoque (L538), Range Rover Sport (L322, L494), Range Rover (L405) vehicles only.



Identify the type of Smart key handset currently fitted -- 'matte' or 'gloss' -- to the vehicle to ensure a like-for-like replacement handset is fitted.


- Left = matte finish
- Right = gloss finish




Remove the chrome cap; place to one side.



Remove the emergency key blade.



Use the emergency key blade to remove and discard the lower case.



Remove the battery from the upper case; place to one side.

6

CAUTION:

Make sure the Printed Circuit Board (PCB) is not damaged when removing the black anti-tamper cover. If the copper coil antenna is damaged, the unit will be unserviceable.



Use a suitable tool to cut the fixings of the black anti-tamper cover and lift away from the Printed Circuit Board (PCB).



Remove the PCB; place to one side.



Remove the key ring retainer; place to one side.



Remove the silicone seal from the lower case; place to one side.

¹ Discard the upper case.



Make sure the foam pads are correctly installed in the lower case as shown.



Install the silicone seal to the upper case.



Install the key ring retainer to the upper case:

Torque: 1Nm.



Make sure the key ring retaining pin is correctly located in the upper case.

14

CAUTION:


Handle only the outer edges of the board when installing the PCB.

NOTE:

The PCB and cover are held in position with the foam pads on the new upper case.




Install the PCB to the upper case.



Install the PCB anti-tamper cover.

NOTE:

16




E162088

Install the lower case onto the handset.



Install the emergency key blade.



Install the chrome cap.

20 Check the operation of the Smart key handset (all functions).

²¹ Perform steps 2-20 as necessary to additional Smart key handsets.