

LTB00968NAS3



TECHNICAL BULLETIN

20 SEP 2017

© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

This reissue replaces all previous versions. Please destroy all previous versions.

Changes are highlighted in blue

SECTION:

310-01: Fuel Tank and Lines

SUBJECT/CONCERN:

Fuel Tank Difficult To Fill

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:	APPLICABILITY:
Range Rover Sport (LW)	2014	001154-001205	Solihull	V6 S/C 3.0L Petrol /V8 S/C 5.0L Petrol
Range Rover Sport (LW)	2014-2015	300003-399999	Solihull	V6 S/C 3.0L Petrol /V8 S/C 5.0L Petrol
Range Rover Sport (LW)	2014-2016	500023-599999	Solihull	V6 S/C 3.0L Petrol /V8 S/C 5.0L Petrol
Range Rover Sport (LW)	2014-2017	600009-685778	Solihull	V6 S/C 3.0L Petrol /V8 S/C 5.0L Petrol
Range Rover Sport (LW)	2016-2017	100000-150686	Solihull	V6 S/C 3.0L Petrol /V8 S/C 5.0L Petrol
Range Rover (LG)	2013-2017	000083-349716	Solihull	V6 S/C 3.0L Petrol /V8 N/A 5.0L Petrol/V8 S/C 5.0L Petrol

MARKETS:NORTH AMERICA

CONDITION SUMMARY:**SITUATION:**

The fuel tank may be difficult to fill.

CAUSE:

This may be caused by the fuel filler pipe design being restrictive.

ACTION:

Should a customer express this concern, follow the Workshop Procedure below.

PARTS:

PART NUMBER	DESCRIPTION	QUANTITY:
LR095804	Fuel Filler Pipe	1
TYG500130	Driveshaft Bolts	4
LR092696	Driveshaft Bolts - 2017MY only	6
LR038196	Bolt	2
LR051047	Bolt	4
LR034277	Nut	2
LR092778	Fuel filler cap - 2013-14MY only	1

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:**NOTES:**

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.
- The JLR Claims Submission System requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Filler neck - Renew	19.55.07	2.3	55	LR062455

NOTE:

Normal Warranty procedures apply.

WORKSHOP PROCEDURE:

-
- 1 Refer to Special Service Message (SSM) SSM72957.
 - Go to Step 2 only if necessary.
 - 2 Remove and discard the fuel filler pipe (see TOPIx Workshop Manual section 310-01: Fuel Tank and Lines).
-

3

NOTE:

2013-14MY vehicles only: discard the old fuel filler cap and install a new fuel filler cap (LR092778) during installation of the new fuel filler pipe.

Install the new fuel filler pipe (LR095804) (see TOPIx Workshop Manual section 310-01: Fuel Tank and Lines).

- 1 **2013-14MY vehicles only:** install new fuel filler cap LR092778.