

Technical Tip

| Topic | 01-15-03TT – DTC P0171 and P2177 – Gasoline Engines Only | | |
|-------------|--|--|--|
| Market area | United States 444 Volkswagen of America, Inc. (6444) | | |
| Brand | Volkswagen | | |
| Date | August 18, 2017 | | |

Condition

ATTENTION:

THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN AS TITLED.

TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.

DTC P0171 and P2177- Gasoline Engines Only

| Model(s) | Year | Eng. Code | Trans. Code | VIN Range From | VIN Range To |
|----------|-----------|---------------------------|-------------|----------------|--------------|
| All | 2009-2018 | All (Gasoline Engines) | All | All | All |

Technical Background

When Diagnosing DTCs P0171 or P2177, monitor MVB 32, field 2 (long term fuel trims).

If fuel trims read 15-20%, excessive ethanol is suspect.

| DTC | Description |
|-------|-----------------------------------|
| P0171 | Fuel Trim Bank 1, System Too Lean |
| P2177 | System Too Lean Off Idle Bank 1 |

Service



Review all repair manual cautions and warnings regarding fuel handling.

Take a fuel sample and check alcohol content.

- 1) In a clear graduated container, mix a 50/50 solution of gasoline from the car and water.
- 2) Shake the container for 30 seconds and allow the solution to settle.
- 3) If the solution settles to a 30/70 (gas/water) mixture and not a 50/50 mixture (see figures 1 and 2), the fuel quality is in question.
- 4) Check the water portion in the solution for clarity. If the water (bottom) portion is foggy, the fuel quality is in question for alcohol contamination (see figures 1 and 2).

1



If excessive ethanol is found, it will be necessary to remove the existing fuel in the tank and replace the fuel using a Top Tier gasoline retailer in your area. Note that on saddle style tanks, fuel on both sides of the fuel tank must be removed. Removing the rear seat will provide access to both the passenger and driver side.

Note:

If the root cause of the concern is determined to be fuel related, the repair and diagnosis will not be covered under warranty.




Figure 1




Figure 2



Additional Information

| Revision History | | | | | | |
|------------------|---------------|--|--|--|--|--|
| Revision Number | Released Date | Reason For Update | | | | |
| 2041646/3 | 8/18/17 | Update to expand fuel testing for lean DTCs. | | | | |
| 2041646/2 | 6/22/17 | Update to latest standard. | | | | |
| 2041646/1 | 8/7/15 | Original publication. | | | | |

© 2017 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

3