

## Service Bulletin

Date: July, 2017

## INFORMATION

## Subject: Information on Unable to Perform Transmission Range Control Module Range Motor Position Learn

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	LaCrosse						
Cadillac	XT5	2017	2018				
Chevrolet	Bolt EV						

Involved Region or Country	North America and N.A. Export Regions			
Condition	Some technicians may comment that they are unable to perform the Transmission Range Control Module (TRCM) Range Motor Position Learn. Some technicians may also find DTC P174D set.			
Cause	This condition may be caused by the transmission temperature being higher or lower that the range requirement of 50-104°F (10-40°C).			
	Important: The technician or service writer should not idle the engine or drive the vehicle before performing the learn procedure. Validate the TRCM has the latest available software.			
Information	⇒ Programming a TRCM does not require learn/setup. the TRCM learn/setup is only required when you have removed/replaced the TRCM, loosened the fasteners to the TRCM mounting bracket, modified the adjustment rod/ linkage (if equipped), or tampered with the interface between the TRCM and the transmission			

Version	2		
Modified	July 19, 2017 - Added the 2018 Model Year, removed the Opel model and changed to Informational bulletin format.		

